



Buy this item and view more at [www.ironplanet.com](http://www.ironplanet.com) or call 800-211-3983

## Item #11535367 - JCB 427 ZX Wheel Loader



### Item Details:

- Features: Enclosed Cab, Air Conditioner, Requires Diesel Exhaust Fluid, Hydraulic Coupler, 106 in Bucket, Forks
- Meter Reading: 2,134 Hours
- Serial # : JCB4A6ACN3079513
- Inspection Completed: 4/3/24





### Shipping Details:







- Location Florida (Tampa-St. Petersburg-Clearwater area)
- Loading Dock Available: No
- Pickup Hours: -
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.

# Inspection Report


**Note:** This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected







General Appearance		
IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		








Serial Number / VIN	JCB4A6ACN3079513	
Paint	No visible damage	
Body Panels	Cab door damaged, Grille damaged, Battery box latch damaged	
Fenders	No visible damage or missing components.	
Steps	Left rear right rear steps damaged	
Hand Rails	No visible damage or missing components	
Exterior Lights		




Wheel Loader* # 1		
Wheel Loader* # 2		
Wheel Loader* # 3		

<b>Safety</b>		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Travel Alarm	Operational	
Horn	Operational	
Seat Belts	Operational	
Safety Lock Out/Stop	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	Yes	












Control Station		
Item	Assessment	Photo
Seat/Armrests	No visible damage or missing components	
Glass	Left cab door shattered	
Mirrors		
Cab Doors	Left door frame damaged	
Steering Controls	★★★★☆	
Hydraulic Controls	★★★★☆	






<p>Drivetrain Controls</p>	<p>★★★★☆</p>	
<p>Dash Console</p>	<p>★★★★☆</p>	
<p>Engine Oil Pressure</p>	<p>The gauge registers in the operating range.</p>	
<p>Warning Lights</p>	<p>Operational, "!" Light in</p>	
<p>Gauges</p>	<p>Operational</p>	
<p>Rear View Camera</p>	<p>Camera operates as intended</p>	
<p>Hour Meter (pre-inspection)</p>	<p>2134 hrs</p>	
<p>Hour Meter</p>	<p>2134 hrs</p>	







Air Conditioner	Operational	
Heater	Operational	
Limited Function Check	The main components are in place and operational as noted.	
Wheel Loader* # 1		
Wheel Loader* # 2		
Wheel Loader* # 3		









<b>Engine</b>		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Engine	No US EPA Label Present Requires Diesel Exhaust Fluid	
Emission Label	No label visible	
A/C Compressor	Operational	
Starter	Operational	
Exhaust System	No visible damage or missing components	
Radiator	★★★★☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	
Cooling System Leaks	No dripping leaks	

Engine - Left Side		
Engine - Right Side		
Limited Function Check	The engine started and ran.	
Engine #1		






<b>Drivetrain</b>		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Transmission	★★☆☆ Operational	
Transfer Case / Drop Box	★★☆☆ Operational	
Front Drive Axle	★★☆☆	
Rear Drive Axle	★★☆☆	
Final Drives	★★☆☆	
Limited Function Check	The drivetrain was operational.	








<b>Hydraulics</b>		
See photos for condition		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses (Hydraulics)	★★★☆☆ Dripping leak hose fitting at valve body	
Loader Lift Cylinders	★★★★☆	
Bucket Tilt Cylinders	★★★★☆	





Auxiliary Hydraulic Plumbing	Not operationally checked, Front	
Steering Cylinders	★★★★☆	
Limited Function Check	The hydraulic system was operational.	
Hydraulics #1		
Hydraulics #2		
Hydraulics #3		
Hydraulics #4		








Chassis		
IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.		
Item	Assessment	Photo
Articulating Center Pins	★★★★☆	
Brake Type	Hydrostatic	
Master Cylinder	★★★★☆	
Brake Lines/Hoses	★★★★☆	
Park Brake	★★★★☆ Stopped from a slow roll	
Limited Function Check - Brakes	The brake system functioned, stopping and holding the machine.	
Frame Condition	★★★★☆	
Left Front Tire	★★★★☆ JCB earthmover 20.5R25 32/32" Tread Depth	
Left Rear Tire	★★★★☆ " " " 29/32" Tread Depth	

Right Rear Tire	★★★★☆ " " " 29/32" Tread Depth	
Right Front Tire	★★★★☆ " " " 32/32" Tread Depth	
Wheel Condition	No visible damage or missing components	
Lift Arm Condition	★★★★☆	
Chassis to Arm Pins	★★★★☆	
Tilt Linkage	★★★★☆	
Tilt Linkage Pins and Bushings	★★★★☆	

Quick Coupler to Arms Pins	☆☆☆☆	
Limited Function Check	The main chassis components were operational in a limited check.	

<b>Specialty</b>		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Specialty #1		

<b>Wheel Loader*</b>		
<b>Item</b>	<b>Assessment</b>	<b>Photo</b>
Loader Bucket Condition	★★★★☆	
Loader Bucket Cutting Edge	★★☆☆☆ Edge worn Not turned	
Loader Quick Coupler	★★★★☆ paladin Coupler, Operational	
Forks	★★★★☆	
Wheel Loader* #1		

Buy this item and view more at [www.ironplanet.com](http://www.ironplanet.com) or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved