



Video:



PHOTOS: Click the link below to view all high resolution images

https://app.aspenfieldservices.com/api/attachments/get/c8NHfutH7wQ5LckZf/full_report_0026506_c8NHfutH7wQ5LckZf.pdf?view

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	2017
Make	Kalmar
Model	DCG250-12LB
Serial Number	A20700139
Type	Fork Lift
Inspection Date	12/30/2020
Location of Business	Sandbox Logistics - 9159 West Hwy 85 , Dilley, TX, 78017, USA
Attachment(s)/ Accessory(s)	Forks
Mismatched Forks	No
Bent Forks	No
Excessive Fork Wear	No
Fork Length (inches)	97"
Fork Width (inches)	9 3/4"
Fork Depth (inches)	4.5"
Power Type	Diesel



Aspen Field Services

Job #: 26506 /

Serial #: A20700139

For more information, visit:

wellsfargo.com/equipmentseller

2017 KALMAR DCG250-12LB

Inspection Details Cont'd	
Transmission	Powershift
Shift Type	Lever
Enclosed Cab	Yes
Engine MFR	Cummins
Controls	Lever
Hours	4434
Cab A-C	Yes
Cab A/C Condition	Good Condition
Cab Heat	Yes
Cab Heat Condition	Good Condition
Backup Camera	Yes
Keyless Ignition	No
Visual Inspection	Clean
Operational Test	Operational
Front Right Tire Part Number	Trelleborg; Not Available
Front Right Tire Condition	Good Condition
Front Right Tire Depth Measurement	27/32"
Front Right Tire Depth Percentage	Above 50 %
Front Right Tire Size	14.00-24
Front Left Tire Part Number	Galaxy; Not Available
Front Left Tire Condition	Good Condition
Front Left Tire Depth Measurement Measurement	24/32"
Front Left Tire Depth Percentage	Above 50%
Front Left Tire Size	14.00-24
Back Right Tire Part Number	Galaxy
Back Right Tire Condition	Gouge
Back Right Tire Tread Depth Measurement	31/32"
Back Right Tire Depth Percentage	Above 50%
Back Right Tire Size	14.00-24
Back Left Tire Part Number	Trelleborg; Not Available
Back Left Tire Condition	Gouge
Back Left Tire Depth Measurement	31/32"
Back Left Tire Depth Percentage	Above 50%
Tilt Cylinders	No Leaks
Lift Cylinders	No Leaks
Mast Operation	Operational
Seat	Tear
Rear Lights	Good Condition
Working Lights	Good Condition
Side Doors	Good Condition

Inspection Details Cont'd	
Side Glass Complete	Cracked
Mufflers	Good Condition
ROPS Condition	Good Condition
Interior	Good Condition
Hydraulic Couplers Present	No
Hydraulic Couplers Visible Damage	No
Engine Compartment	Dirty
Roller Wear	No
Side Shift Present	Yes
Side Shift Operational	Operational
Customer Decals Visible on Unit	No
Back Left Tire Size	Not Available
Mismatched Tires	Yes
Comments	The front glass is cracked.