



Video:



PHOTOS: Click the link below to view all high resolution images

https://app.aspenfieldservices.com/api/attachments/get/wfvvpd5vr8GKixWKi/report_0025116_wfvvpd5vr8GKixWKi.pdf

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

| Inspection Details | |
|-----------------------------|---|
| Year | 2016 |
| Make | Shuttlewagon |
| Model | NVX6030 |
| Serial Number | 603016033 |
| Type | Mobile Railcar Mover |
| Inspection Date | 10/15/2020 |
| Location of Business | JJ Kane Auctioneers - 100 Liberty Rd, Villa Rica, GA 30180, USA |
| Attachment(s)/ Accessory(s) | None |
| Enclosed Cab | Yes |
| Engine MFR | Not Visible (worn off) |
| Controls | Standard |
| Hours | 6233 |
| Cab A-C | Yes |
| Cab Heat | Yes |
| Keyless Start | No |



Aspen Field Services

Job #: 25116 /

Serial #: 603016033A

For more information, visit:

wellsfargo.com/equipmentseller

2016 SHUTTLEWAGON NVX6030

| Inspection Details Cont'd | |
|------------------------------------|---|
| Visual Inspection | Clean |
| Operational Test | Operational |
| Front Right Tire Part Number | Rockstar: Not Available |
| Front Right Tire Condition | Good Condition |
| Front Right Tire Depth Measurement | 1 7/8" |
| Front Right Tire Size | 14.00-24 |
| Front Left Tire Part Number | Rockstar: Not Available |
| Front Left Tire Condition | Good Condition |
| Front Left Tire Depth Measurement | 1 7/8" |
| Front Left Tire Size | 14.00-24 |
| Back Right Tire Part Number | Rockstar: Not Available |
| Back Right Tire Condition | Good Condition |
| Back Right Tire Depth Measurement | 2" |
| Back Right Tire Size | 14.00-24 |
| Back Left Tire Part Number | Rockstar: Not Available |
| Back Left Tire Condition | Good Condition |
| Back Left Tire Depth Measurement | 2" |
| Back Left Tire Size | 14.00-24 |
| Back Left Drive Hub | Good Condition |
| Back Right Right Drive Hub | Good Condition |
| Front Left Drive Hub | Good Condition |
| Front Right Drive Hub | Good Condition |
| Front Coupler Lift Cylinder | Good Condition |
| Rear Coupler Lift Cylinder | Good Condition |
| Wheel Cylinder | Good Condition |
| Tailgate Lights | Good Condition |
| Working Lights | Non Operational |
| Cab Door | Good Condition |
| Side Glass Complete | Good Condition |
| Seat | Ripped |
| Mufflers | Good Condition |
| Intake Screen | Good Condition |
| Engine Compartment | Dirty |
| Customer Decals Visible on Unit | None |
| Air Tank | Good Condition |
| Comments | The front right brake light is non operational. |

Inspection Details Cont'd