

2022 VERMEER CTX100

UNIT: 1VRZ080HCN1004748

[Download Reconditioning Printout](#)







UNIT SPECS

Customer

Wells Fargo (IMS)

LOCATION

Wells Fargo (IMS)



Please call Pickup Support for location information
Davenport, FL 33897

GENERAL APPEARANCE

Serial Number / VIN

1VRZ080HCN1004748



Pre-Operational Checks

Confirm Fluids Checked: Engine Coolant. Confirm Fluids Checked: Engine(s) Oil. Confirm Fluids Checked: Hydraulic Fluid. Confirm Fluids Checked: Fuel Level. N/A: Transmission Fluid



Paint

No visible damage



Cab/Canopy Overhead Structural Framework

No visible damage

☐ ☐

Hand Rails

No visible damage or missing components

☐ ☐

Year

2022

☐ ☐

Make

Vermeer

☐ ☐

Model

CTX100

☐ ☐

Body Panels

Top engine cover damaged, Grille damaged

☐ ☐

Steps

No visible damage or missing components

☐ ☐

SAFETY

Safety Lock Out/Stop

Operational

☐ ☐

Current Safety Manual

No

☐ ☐

Current Operator/Maintenance Manual

Yes

☐ ☐

CONTROL STATION

Steering Controls

Rating:

Good

☐ ☐

Hydraulic Controls

Rating:

Good



Auxiliary Hydraulic Control

Rating:

Good



Drivetrain Controls

Rating:

Good



Warning Lights

Operational



Dash Console

Rating:

Good



Engine Oil Pressure

No oil pressure indicator



Hour Meter (Pre-inspection)

356 hrs



Hour Meter

357 hrs



Limited Function Check (Control Station)

The main components are in place and operational as noted.



Control Station

Open Operator Station



ENGINE

Starter

Operational



Exhaust System

No visible damage or missing components



Radiator

Rating:

Good



Oil Leaks

No dripping leaks



Fuel Leaks

No dripping leaks



Cooling System Leaks

No dripping leaks



Limited Function Check (Engine)

The engine started and ran.



Engine

2021 US EPA Label



DRIVETRAIN

Drive Motors

Rating:

Good



Final Drives

Rating:

Good



Limited Function Check (Drivetrain)

The drivetrain was operational.



HYDRAULICS

Pumps (Hydraulics)

Rating:

Good



Valves

Rating:

Good



Hydraulic Tank

Rating:

Good



Hoses (Hydraulics)

Rating:

Good



Auxiliary Hydraulic Plumbing

Seepage, Not operationally checked



Loader Lift Cylinders

Rating:

Good



Bucket Tilt Cylinders

Rating:

Good



Limited Function Check (Hydraulics)

The hydraulic system was operational.



CHASSIS

Frame Condition

Rating:

Good



Lift Arm Condition

Rating:

Good



Chassis to Arm Pins

Rating:

Good



Quick Coupler To Arms Pins

Rating:

Good



Limited Function Check (Chassis)

The main chassis components were operational in a limited check.



SPECIALTY

Front Attachment

Front Attachment Details, Quick Coupler Type: Manual Coupler



Loader Bucket Condition

No bucket included



Quick Coupler

Rating:

Good



LOGISTICS INFORMATION

General Shipping Information

Yes: Does this Unit Run? Yes: If self propelled, does the unit travel? No: Is the unit taller than 12'? No: Is the unit wider than 8'6"? No: Inflated Tires - item can roll? No: Noticeable fluid leaks?



MODEL DESCRIPTION

Model Description

Mini



RUBBER TRACK UNDERCARRIAGE

Roller Frames

Rating:

Good



Grouser Height Measurement

Left side: 8 mm, Right side: 7 mm



Rubber Belt Drive Lugs

No visible damage
☐ ☐
Track Tensioners
Operational
☐ ☐

RECONDITIONING

Top Engine Cover Damaged	\$1,000
--------------------------	---------

Grille Damaged	\$750
----------------	-------

Total	\$1,750
-------	---------