



Video:



PHOTOS: Click the link below to view all high resolution images

[https://app.aspenfieldservices.com/api/attachments/get/Ys53GbQSQ3BqNBZ4z/full\\_report\\_0027082\\_Ys53GbQSQ3BqNBZ4z.pdf?view](https://app.aspenfieldservices.com/api/attachments/get/Ys53GbQSQ3BqNBZ4z/full_report_0027082_Ys53GbQSQ3BqNBZ4z.pdf?view)

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	2015
Make	Shuttlewagon
Model	NVX5025
Serial Number	502515071
Type	Railcar
Inspection Date	1/8/2021
Location of Business	JJ Kane Auctioneers -2157 NE Jacksonville Rd , Ocala, FL, 34470, USA
Attachment(s)/ Accessory(s)	None
Enclosed Cab	Yes
Driver Seat	Good Condition
Passenger Seat	Cut
Controls	Standard
Keyless Start	None
Foot Pedals	Good Condition
Hours	14518



# Aspen Field Services

Job #: 27082 /

Serial #: 502515071

For more information, visit:

[wellsfargo.com/equipmentseller](http://wellsfargo.com/equipmentseller)

2015 NVX5025 SHUTTLEWAGON RAILCAR

Inspection Details Cont'd	
Cab A-C	Yes
Cab Heat	Yes
Cab A/C Condition	Good Condition
Cab Heat Condition	Good Condition
Backup Camera	Yes
Visual Inspection	Clean
Operational Test	Operational
Front Right Tire Part Number	Michelin: Not Available
Front Right Tire Size	14.00R24
Front Right Tire Condition	Cut
Front Right Tire Depth Measurement	6/32"
Front Left Tire Part Number	Michelin: Not Available
Front Left Tire Size	14.00R24
Front Left Tire Condition	Gouge
Front Left Tire Depth Measurement	2/32"
Back Right Tire Part Number	Bridgestone: Not Available
Back Right Tire Size	14.00R24
Back Right Tire Condition	Good Condition
Back Right Tire Depth Measurement	1/32"
Back Left Tire Part Number	Michelin: Not Available
Back Left Tire Size	Not Visible
Back Left Tire Condition	Good Condition
Back Left Tire Depth Measurement	5/32"
Front Right Drive Hub	Good Condition
Front Left Drive Hub	Good Condition
Back Right Drive Hub	Good Condition
Back Left Drive Hub	Good Condition
Front Coupler Lift Cylinder	Good Condition
Rear Coupler Lift Cylinder	Good Condition
Rear Wheel Hydraulics	Good Condition
Front Wheel Hydraulics	Good Condition
Tailgate Lights	Non Operational
Working Lights	Good Condition
Cab Door	Good Condition
Passenger Door	Good Condition
Side Glass Complete	Good Condition
Muffler	Good Condition
Intake Screen	Good Condition
Engine Door	Good Condition
Engine Compartment	Dirty

Inspection Details Cont'd	
Engine MFR	Cummins
Engine Serial Number	73824021
Customer Decals Visible on Unit	No
Railings	Good Condition
Steps	Good Condition
Comments	The left tailgate light is non operational. All of the tires are worn down and need to be replaced.