

# CONSTRUCTION EQUIPMENT CONDITION REPORT

For more information, visit:  
wellsfargo.com/equipseller



**Commerical Vehicle Inspection Group**  
Truck, Tractor, Trailer, and Equipment  
Inspections throughout North America  
203-628-4325 info@cvigna.com

Make: Komatsu	Type: DOZER	Inspector: GP
Model: D61PXi24	Hours: 7108	
SN: KMT0D129LKBB60997	Year: 2019	Inspection Date: 8/30/2024

## SPECIFICATIONS

<b>Tracks</b>	Tracks Model: <b>SINGLE GROUSER</b>	Cut: <b>No</b>	Controls: <b>FWD - REV - LEFT - RIGHT - RAISE / LOWER CUTTER</b>
	Tread Depth: <b>80/32</b>	Tread %: <b>Over 50%</b>	
Enclosed Cab: <b>Yes</b>	Heat: <b>Yes</b>	A/C: <b>Yes</b>	
Bucket Width: <b>152</b>	Teeth: <b>Without</b>	Damaged: <b>No</b>	
Other Options:	<b>12'6" BLADE- TILTS AND SWINGS SIDE TO SIDE REAR CAMERA</b>		

## CONDITION REPORT

Check	Comments / Deficiencies
✓ Frame	
✓ Boom & Uprights	
✓ Lift Cylinders	
✓ Tilt Cylinders	
✓ R H Drive	
✓ L H Drive	
✓ Variable Speed	
✓ Engine	QUIET
✓ Appearance	GOOD
N/A Describe Missing Parts	
✓ Attachment Inspection	
X Condition Report	REAR VIEW MIRROR MISSING
X Condition Report	LEFT SIDE OF CAB BENT / DENTED AT BOTTOM
X Condition Report	EXHAUST PIPE TURN OUT MISSING
X Condition Report	CARRIER ROLLERS WORN

PHOTOS



Seating / Interior



Rear



Front Right



Front Left



PHOTOS





PHOTOS





PHOTOS



PHOTOS





PHOTOS



PHOTOS





PHOTOS

