



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #9801441 - 2019 Wacker Neuson WL38 Wheel Loader



Item Details:

- Features: Enclosed Cab, Air Conditioner, Hydraulic Coupler, 72 in
- Meter Reading: 854 Hours
- Serial # : 3046489
- Inspection Completed: 5/3/23

Shipping Details:

- Location Missouri (Scott County)
- Loading Dock Available: No
- Pickup Hours: -

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key

★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Serial Number / VIN	3046489	
Paint	feed lot corrosion	
Body Panels	No visible damage or missing components.	
Fenders	No visible damage or missing components.	
Steps	No visible damage or missing components.	

Hand Rails	No visible damage or missing components	
Exterior Lights	All lights operational	
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Front Corner		
Picture, Right Rear Corner		
Wheel Loader* # 1		

Wheel Loader* # 2		
Wheel Loader* # 3		
Wheel Loader* # 4		

Safety		
Item	Assessment	Photo
Travel Alarm	Inoperable	
Horn	Inoperable	
Seat Belts	Operational	
Safety Lock Out/Stop	Inoperable	
Current Safety Manual	No	
Current Operator/Maintenance Manual	No	


Control Station		
Item	Assessment	Photo
Seat/Armrests	No visible damage or missing components	
Glass	No visible damage or missing components	
Mirrors		
Cab Doors	No visible damage or missing components	
Steering Controls	★★★★☆	
Hydraulic Controls	★★★★☆	

Drivetrain Controls	★★★★☆	
Dash Console	★★★★☆	
Warning Lights	Operational	
Gauges	Operational	
Hour Meter (pre-inspection)	854 hrs	
Hour Meter	854 hrs, Operational hour meter	
Heater	Not operationally checked	
Limited Function Check	The item was not operational. Ratings are based on a static inspection.	

Wheel Loader* # 1		
-------------------	--	---

Engine		
Item	Assessment	Photo
Engine	No US EPA Label Present	
Starter	Inoperable	
Exhaust System	No visible damage or missing components	
Engine - Left Side		
Engine - Right Side		
Limited Function Check	There was no response from the engine when the key was turned. Hood hinges are corroded and will not articulate completely open	
Engine #1		
Engine #2		

Drivetrain		
Item	Assessment	Photo
Transmission	★★★★☆	
Transfer Case / Drop Box	★★★★☆	
Front Drive Axle	★★★★☆	
Rear Drive Axle	★★★★☆	
Final Drives	★★★★☆	
Limited Function Check	The drivetrain could not be operationally checked.	
Drivetrain #1		

Hydraulics		
See photos for condition		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hoses (Hydraulics)	★★★★☆	
Loader Lift Cylinders	★★★★☆	
Bucket Tilt Cylinders	★★★★☆	
Auxiliary Hydraulic Plumbing	Not operationally checked, Front	
Steering Cylinders	★★★★☆	
Limited Function Check	The hydraulic system could not be operationally checked.	
Hydraulics #1		

Chassis



IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Articulating Center Pins	★★★★☆	
Brake Type	Hydrostatic	
Master Cylinder	★★★★☆	
Brake Lines/Hoses	★★★★☆ Not operationally checked	
Limited Function Check - Brakes	The brakes were not operationally checked.	
Frame Condition	★★★★☆	
Left Front Tire	★★★★☆ Alliance 385/55R18 30/32" Tread Depth	
Left Rear Tire	★★★★☆ Alliance 385/55R18 28/32" Tread Depth	

Right Rear Tire	★★★★☆ Alliance 385/55R18 28/32" Tread Depth	
Right Front Tire	★★★★☆ Alliance 385/55R18 30/32" Tread Depth	
Wheel Condition	No visible damage or missing components	
Lift Arm Condition	★★★★☆	
Chassis to Arm Pins	★★★★☆	
Tilt Linkage	★★★★☆	
Tilt Linkage Pins and Bushings	★★★★☆	

Quick Coupler to Arms Pins	★★★★☆	
Limited Function Check	The unit could not be started. Several components could not be checked.	
Chassis #1		
Chassis #2		
Chassis #3		
Chassis #4		

Specialty		
Item	Assessment	Photo
Specialty #1		

Wheel Loader*		
Item	Assessment	Photo
Loader Bucket Condition	★★☆☆☆ Corrosion	
Loader Bucket Cutting Edge	★★☆☆☆ Edge worn	
Loader Quick Coupler	★★☆☆☆ Not operationally checked	
Wheel Loader* #1		
Wheel Loader* #2		
Wheel Loader* #3		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved