



Video:



PHOTOS: Click the link below to view all high resolution images

https://app.aspenfieldservices.com/api/attachments/get/xT4wNq9GQnKAq7Nh3/full_report_0042715_xT4wNq9GQnKAq7Nh3.pdf?view

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	2016
Make	Leeboy
Model	8515
Date of Inspection	06/08/2022
Location of Inspection	200 Altec Way, Mount Airy, NC, 27030, USA
VIN	148558
GVWR	NA Obstructed
Hours	1,074
EMS Panel	No Warnings
Interior	Good Condition
Driver Seat	Damaged
Transmission Type	Hydraulic
Dash	Good Condition
Switches	Good Condition
Joystick	Good Condition



Aspen Field Services

Job #: 42715 /

Serial #: 8515-148558

2016 LEEBOY 8515D PAVER

For more information, visit:

wellsfargo.com/equipmentseller

Inspection Details Cont'd	
Pedals	NA Obstructed
Floorboard	NA Obstructed
Steps	Good Condition
Engine Compartment	Good Condition
Oil Dipstick	Low
Coolant Reservoir	Good Condition
Front Lights	Good Condition
Exhaust Pipe	Good Condition
Lift Cylinders	Good Condition
Cylinders	Good Condition
Electric Heat Power	Good Condition
Intake Screen	Good Condition
Hydraulic Hoses	Good Condition
Hydraulic Fluids	Good Condition
Hydraulic Housing	Good Condition
Feeder Conveyor	Good Condition
SMV Decals	Poor Condition
Hopper Decals	Poor Condition
Screed	Damaged
Rear Lights	Damaged
Hydraulic Lines	Good Condition
Actuator	Good Condition
Comments	The tracks were not accessible. The slow moving vehicle decal is damaged at the right seat. The left operator seat is torn on the bottom cushion. The back rest cushion at the right operator seat is missing. The hopper rubber flashing is worn out. The right rear light is broken. The protective shield over the hydraulic lines located at the operator seat base is torn. The engine oil is low according to the oil dipstick. The decals are peeling off on the hopper area. The guide arm is rubbing against the paver causing damage to the paint. The real VIN and unit model information were slightly different from the ones provided. There is no active warnings on this unit. The rear screed step is bent downwards.

Inspection Details Cont'd