



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #11535314 - JCB 220XL 4F Tracked Excavator



Item Details:

- Features: Air Conditioner, Straight Travel Pedal, Rear View Camera, 2022 US EPA Label, Requires Diesel Exhaust Fluid, 9 ft 11 in Stick, Auxiliary Hydraulic Plumbing, Hydraulic Quick Coupler, 45.5 in Digging Bucket
- Meter Reading: 971 Hours
- Serial # : JCBA220GLN2874932
- Inspection Completed: 4/3/24





Shipping Details:

- Location Florida (Tampa-St. Petersburg-Clearwater area)
- Loading Dock Available: No
- Pickup Hours: -
- You will need a copy of your IronPlanet Item Release to pick the item up. Please call one day in advance to schedule pickup.


Inspection Report







Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.







Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected




General Appearance		
Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		







<p>Serial Number / VIN</p>	<p>JCBA220GLN2874932</p>	
<p>Paint</p>	<p>No visible damage</p>	
<p>Body Panels</p>	<p>No visible damage or missing components</p>	
<p>Steps</p>	<p>No visible damage or missing components</p>	
<p>Hand Rails</p>	<p>No visible damage or missing components</p>	
<p>Exterior Lights</p>	<p>1 Inoperable / damaged / missing Boom light inoperable</p>	







Safety		
Item	Assessment	Photo
Travel Alarm	Operational	
Horn	Operational	
Seat Belts	Operational	
Safety Lock Out/Stop	Operational	
Swing Brake	Operational	
Current Safety Manual	No	
Current Operator/Maintenance Manual	Yes	





Control Station		
Item	Assessment	Photo
Seat/Armrests	No visible damage or missing components	
Glass	No visible damage or missing components	
Mirrors		
Cab Door	No visible damage or missing components	
Steering Controls	★★★★☆	
Hydraulic Controls	★★★★☆	







Drivetrain Controls	★★★★☆	
Dash Console	★★★★☆	
Engine Oil Pressure	No oil pressure indicator	
Warning Lights	Operational	
Gauges	Operational	
Rear View Camera	Camera operates as intended	
Hour Meter (pre-inspection)	971 hrs	
Hour Meter	971 hrs	
Air Conditioner	Operational	
Heater	Operational	
Limited Function Check	The main components are in place and operational as noted.	






Excavator* # 1		 A close-up photograph of a handheld device, likely a tablet or smartphone, displaying a 'Machine Overview' screen. The screen shows 'Machine Hours 960 h' and 'VIN JCBAA220GLN2874932'. The 'IRON PLANET' logo is visible in the bottom right corner of the device's frame.
Excavator* # 2		 A close-up photograph of the excavator's control lever, which is black with a yellow grip. The lever is mounted on a grey control panel. In the background, the yellow boom of the excavator is visible, featuring the 'JCB' logo. The 'IRON PLANET' logo is visible in the bottom right corner of the image.
Excavator* # 3		 A wide-angle photograph of the excavator's operator's cab. The cab is grey with yellow accents. A large touchscreen display is mounted on the dashboard. Two circular gauges with yellow surrounds are visible on the left side of the dashboard. The 'IRON PLANET' logo is visible in the bottom right corner of the image.







Engine		
Item	Assessment	Photo
Engine	2022 US EPA Label, Requires Diesel Exhaust Fluid	
Emission Label		
A/C Compressor	Operational	
Starter	Operational	
Exhaust System	No visible damage or missing components	
Radiator	☆☆☆☆	
Oil Leaks	No dripping leaks	
Fuel Leaks	No dripping leaks	

Cooling System Leaks	No dripping leaks	
Engine - Left Side		
Engine - Right Side		
DEF / AdBlue Tank		
Limited Function Check	The engine started and ran. Relay box and battery box covers removed.	
Engine #1		
Engine #2		

Drivetrain		
Operational test is limited to low speed in a confined flat area without load. Differential interlocks, full transmission shifting and functionality of all drive axles cannot be fully verified. Inspector listens for abnormal noises, observes leaks and notes physical damage.		
Item	Assessment	Photo
Left Drive Motor	★★★★☆	
Right Drive Motor	★★★★☆	
Left Final Drive	★★★★☆	
Right Final Drive	★★★★☆	
Limited Function Check	The drivetrain was operational.	







Hydraulics		
Item	Assessment	Photo
Pumps (Hydraulics)	★★★★☆	
Valves	★★★★☆	
Hydraulic Tank	★★★★☆	
Hoses (Hydraulics)	★★★★☆	
Auxiliary Hydraulic Plumbing	Not operationally checked, End of stick	
Swing Motor	★★★★☆	








Hydraulic Center Swivel	★★★★☆	
Boom Lift Cylinder(s)	★★★★☆	
Stick Cylinder	★★★★☆	
Bucket Cylinder	★★★★☆	
Limited Function Check	The hydraulic system was operational.	
Excavator_2 # 1		








Chassis		
Item	Assessment	Photo
Boom Condition	★★★★☆	
Stick Condition	★★★★☆	
Boom Base Pin and Bushings	★★★★☆	
Pin and Bushings Boom to Stick	★★★★☆	
Pins and Bushings Stick to Coupler	★★★★☆	
Turntable Bearing	★★★★☆	
Bottom Covers	★★★★☆	
Limited Function Check	The main components were operational in a limited check.	




Excavator* # 1







Undercarriage		
Undercarriage components photos (links, bushings, sprockets, idlers, rollers, grousers) are selected as representative. Bidders are encouraged to review photos using the zoom feature to judge condition in detail.		
Item	Assessment	Photo
Track Link Brand	No mark	
Left Roller Frame	★★★☆☆	
Left Track Tensioner	★★★☆☆	
Left Track Pads	★★★☆☆ 31.6 in Wide Triple Grouser	
Left Grouser Height	30 mm	
Left Track Links	105 mm	
Left Track Bushings	58 mm	

Left Carrier Rollers	#1 118 mm #2 119 mm	
Left Bottom Rollers	#1 148 mm #2 148 mm #4 148 mm #5 148 mm #7 148 mm #8 148 mm	
Left Idler		
Left Sprocket	★★★★☆	
Right Roller Frame	★★★★☆	
Right Track Tensioner	★★★★☆	
Right Track Pads	31.6 in Wide Triple Grouser	

Right Grouser Height	29 mm	
Right Track Links	195 mm	
Right Track Bushings	58 mm	
Right Carrier Rollers	#1 119 mm #2 118 mm	
Right Bottom Rollers	#1 148 mm #2 148 mm #4 148 mm #5 148 mm #7 148 mm #8 148 mm	
Right Idler		
Right Sprocket	★★★★☆	

Undercarriage #1		
Undercarriage #2		
Undercarriage #3		

Specialty		
Item	Assessment	Photo
Excavator Bucket Condition	★★☆☆ Bottom of bucket pushed in	
Bucket Cutting Edge/Shanks/Teeth	★★★☆ No visible damage or missing components	
Quick Coupler	★★★☆ Operational	
Excavator_2 # 1		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved