



Video:



**PHOTOS:** Click the link below to view all high resolution images

[https://app.aspenfieldservices.com/api/attachments/get/wM8uhT9ayqwChw5sZ/full\\_report\\_0026185\\_wM8uhT9ayqwChw5sZ.pdf?view](https://app.aspenfieldservices.com/api/attachments/get/wM8uhT9ayqwChw5sZ/full_report_0026185_wM8uhT9ayqwChw5sZ.pdf?view)

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	2015
Make	Shuttlewagon
Model	SWX315
Serial Number	31515061
Type	Railcar
Inspection Date	12/4/2020
Location of Business	JJ Kane Auctioneers - 2157 NE Jacksonville Rd , Ocala, FL, 34470, USA
Attachment(s)/ Accessory(s)	None
Enclosed Cab	Yes
Controls	Standard
Hours	1077
Cab A-C	Yes
Cab Heat	Yes
Keyless Start	No
Visual Inspection	Clean



# Aspen Field Services

Job #: 26185 /

Serial #: 31515061

2015 SWX315 SHUTTLEWAGON

For more information, visit:

[wellsfargo.com/equipmentseller](http://wellsfargo.com/equipmentseller)

Inspection Details Cont'd	
Operational Test	Operational
Front Right Tire Part Number	Michelin: Not Available
Front Right Tire Condition	Good Condition
Front Right Tire Depth Measurement	28/32"
Front Right Tire Size	315/80 R 22.5
Front Left Tire Part Number	Michelin: Not Available
Front Left Tire Condition	Good Condition
Front Left Tire Depth Measurement	24/32"
Front Left Tire Size	315/80 R 22.5
Back Right Tire Part Number	Michelin: Not Available
Back Right Tire Condition	Good Condition
Back Right Tire Depth Measurement	27/32"
Back Right Tire Size	315/80 R 22.5
Back Left Tire Part Number	Goodyear: Not Available
Back Left Tire Condition	Good Condition
Back Left Tire Depth Measurement	29/32"
Back Left Tire Size	315/80R22.5
Back Left Drive Hub	Good Condition
Back Right Drive Hub	Good Condition
Front Left Drive Hub	Good Condition
Front Right Drive Hub	Good Condition
Front Coupler Lift Cylinder	Good Condition
Rear Coupler Lift Cylinder	Good Condition
Tailgate Lights	Good Condition
Working Lights	Good Condition
Cab Door	Good Condition
Side Glass Complete	Good Condition
Seat	Good Condition
Muffler	Good Condition
Intake Screen	Good Condition
Engine Compartment	Dirty
Engine MFR	Not Visible
Customer Decals Visible on Unit	No
Air Tank	Good Condition
Backup Camera	No
Mismatched Tires	Yes
Cab A-C Condition	Good Condition
Cab Heat Condition	Good Condition
Comments	

## Inspection Details Cont'd