



Video:



PHOTOS: Click the link below to view all high resolution images

https://app.aspenfieldservices.com/api/attachments/get/WYACfthYdiexX679t/report_0024410_WYACfthYdiexX679t.pdf

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	2016
Make	Kalmar
Model	Ottawa T2
Serial Number	11VJ813A2GA001104
Inspection Date	09/23/2020
Location of Business	JJ Kane Auctioneers - Waxahachie; 999 Solon Rd , Waxahachie, TX, 75165, USA
Hours	45507
Cab A-C	Yes
Cab Heat	Yes
Seat	Damaged
Tailgate Lights	Operational
Working Lights	Operational
Side Glass Complete	Yes
Interior Color	Gray
Customer Decals Visible on Unit	Yes



Aspen Field Services

Job #: 24410 /

Serial #: 11VJ813A2GA001104

For more information, visit:

wellsfargo.com/equipmentseller

2016 OTTAWA 4X2 DOT YARD TRUCK

Inspection Details Cont'd	
Transmission Make	Allison
Transmission Model	Not Available
Power Windows	Yes
Fuel Type	Diesel
Fuel Tank Material	Steel
5th Wheel Type	Air Slide
Window Glass Condition	Good
Windshield Condition	Good
Mirror Glass Condition	Good
Frame Material	Steel
Upholstery	Leather
Paint Condition	Good
Exterior Color	White
Exhaust	Stack
Front Right Steer Wheel Type	Steel
Front Right Steer Wheel Condition	Good
Front Right Steer Tire Depth	8/32"
Front Right Steer Tire Condition	Good
Rear Right Drive Wheel Type Inner	Steel
Rear Right Drive Wheel Condition Inner	Good
Rear Right Drive Tire Depth Inner	2/32"
Rear Right Drive Tire Condition Inner	Replacement Needed
Rear Right Drive Wheel Type Outer	Steel
Rear Right Drive Wheel Condition Outer	Good
Rear Right Drive Tire Depth Outer	15/32"
Rear Right Drive Tire Condition Outer	Good
Front Left Steer Wheel Type	Steel
Front Left Steer Wheel Condition	Good
Front Left Steer Tire Depth	4/32"
Front Left Steer Tire Condition	Replacement Needed
Rear Left Drive Wheel Type Inner	Steel
Rear Left Drive Wheel Condition Inner	Good
Rear Left Drive Tire Depth Inner	18/32"
Rear Left Drive Tire Condition	Good
Rear Left Drive Wheel Type	Steel
Rear Left Drive Wheel Condition	Good
Rear Left Drive Tire Depth	12/32"
Rear Left Drive Tire Condition	Good
Mud Flaps	Yes

Inspection Details Cont'd	
Mismatched Tires	Yes
Operations	Passed
Comments	There is a dent on the front right corner. The window handle knob is missing.