

# CONSTRUCTION EQUIPMENT CONDITION REPORT

For more information, visit:  
wellsfargo.com/equipseller



**Commerical Vehicle Inspection Group**  
Truck, Tractor, Trailer, and Equipment  
Inspections throughout North America  
203-628-4325 info@cvigna.com

Make:	Komatsu	Type:	EXCAVATOR	Inspector:	GP
Model:	PC360LC-11	Hours:	8002	Inspection Date:	8/30/2024
SN:	KMTPC256KKWA37338	Year:	2019		

## SPECIFICATIONS

<b>Tracks</b>	Tracks Model:	<b>TRIPLE GROUSER</b>	Cut:	<b>No</b>	Controls:	<b>FWD - REV - LEFT - RIGHT - RAISE / LOWER CUTTER</b>
	Tread Depth:	<b>54/32</b>	Tread %:	<b>Over 50%</b>		
Enclosed Cab:	<b>Yes</b>	Heat:	<b>Yes</b>	A/C:	<b>Yes</b>	
Bucket Width:	<b>63</b>	Teeth:	<b>With</b>	Damaged:	<b>No</b>	
Other Options:	<b>REAR CAMERA</b>					

## CONDITION REPORT

	Check	Comments / Deficiencies
✓	Frame	
✓	Boom & Uprights	
✓	Lift Cylinders	
✓	Tilt Cylinders	
✓	R H Drive	QUIET
✓	L H Drive	QUIET
✓	Variable Speed	QUIET
X	Engine	QUIET - ENGINE FAULT CODE PRESENT - DIAGNOSE
✓	Appearance	AVERAGE
N/A	Describe Missing Parts	
✓	Attachment Inspection	NOTE - NEW PINS IN BUCKET LINKAGE - NEW TEETH ON BUCKET
X	Condition Report	ENGINE COVER LATCH MISSING
X	Condition Report	YELLOW SAFETY WARNING BEACON BROKEN
X	Condition Report	LEFT CAB DOOR BENT / SPRUNG AT BOTTOM

PHOTOS



Seating / Interior



Rear



Front Left



Front Right



PHOTOS



PHOTOS





PHOTOS





PHOTOS



PHOTOS





PHOTOS





PHOTOS

