

Aspen Field Services

Job #: 26509 / Serial #: A20700175

For more information, visit: wellsfargo.com/equipmentseller









Video:



PHOTOS: Click the link below to view all high resolution images

https://app.aspenfieldservices.com/api/attachments/get/
AFBiggW8WwteX9Azw/full_report_0026509_AFBiggW8WwteX9Azw.pdf?
view

Inspection Details Year 2017 Make Kalmar DCG250-12 Model A20700175 Serial Number Type Fork Lift Inspection Date 1/30/2021 Location of Business Sandbox Logistics - 9159 West Hwy 85, Dilley, TX, 78017, USA Attachment(s)/ None Accessory(s) Mismatched Forks No Bent Forks No **Excessive Fork Wear** No Fork Length (inches) 96" Fork Width (inches) 9.5" Fork Depth (inches) 4" Power Type Diesel

NOTE: By clicking above, you will be redirected to Aspen Field Services'



Aspen Field Services Job #: 26509 / Serial #: A20700175

For more information, visit: wellsfargo.com/equipmentseller

website, not a Wells Fargo property.



Aspen Field Services

Job #: 26509 / SPEN Serial #: A20700175

For more information, visit: wellsfargo.com/equipmentseller

Inspection Details Cont'd	
Transmission Type	Powershift
Shift Type	Lever
Enclosed Cab	Yes
Engine MFR	Cummins
Controls	Lever
Hours	3077
Cab A-C	Yes
Cab A/C Condition	Good Condition
Cab Heat	Yes
Cab Heat Condition	Good Condition
Keyless Ignition	None
Visual Inspection	Clean
Operational Test	Operational
Front Right Tire Part Number	Continental: Not Available
Front Right Tire Condition	Good Condition
Front Right Tire Depth Measurement	1"
Front Right Tire Depth Percentage	Above 50%
Front Right Tire Size	14.00-24
Front Left Tire Part Number	Continental: Not Available
Front Left Tire Condition	Good Condition
Front Left Tire Depth Measurement	1 1/2"
Front Left Tire Depth Percentage	Above 50%
Front Left Tire Size	14.00-24
Back Right Tire Part Number	Continental: Not Available
Back Right Tire Condition	Good Condition
Back Right Tire Depth Measurement	1 3/4"
Back Right Tire Depth Percentage	Above 50%
Back Right Tire Size	14.00-24
Back Left Tire Part Number	Continental: Not Available
Back Left Tire Condition	Cut
Back Left Tire Depth Measurement	1 1/2"
Back Left Tire Depth Percentage	Above 50%
Back Left Tire Size	14.00-24
Mismatched Tires	No
Tilt Cylinders	No
Lift Cylinders	No Leaks
Mast Operation	Operational
Seat	
	Tear
Rear Lights	Tear Good Condition

Inspection Details Cont'd	
Side Doors	Good Condition
Side Glass Complete	Yes
Mufflers	Good Condition
ROPS Condition	Good Condition
Interior	Fair
Hydraulic Couplers Present	No
Hydraulic Couplers Visible Damage	No
Engine Compartment	Dirty
Roller Wear	No
Side Shift Present	Yes
Side Shift Operational	Operational
Customer Decals Visible on Unit	No
Comments	The head rest is missing.