



Video:



PHOTOS: Click the link below to view all high resolution images

https://app.aspenfieldservices.com/api/attachments/get/5aJqYAcTAfPP4B5iW/report_0024406_5aJqYAcTAfPP4B5iW.pdf

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

| Inspection Details | |
|----------------------|---|
| Master Lease Number | 001-0436024-106 |
| Year | 2017 |
| Make | Hamm |
| Model | HD120i VV HF |
| Serial Number | H2430057 |
| Type | Roller |
| Inspection Date | 9/16/2020 |
| Location of Business | JJ Kane Auctioneers - 95 3rd St NE , Graysville, AL, 35073, USA |
| Attachment(s) | None |
| Enclosed Cab | No |
| Engine MFR | Deutz |
| Controls | Standard |
| Hours | 2155 |
| Cab A-C | No |
| Cab Heat | No |



Aspen Field Services

Job #: 24406 /

Serial #: H2430057

2017 HD120I VV HF

For more information, visit:

wellsfargo.com/equipmentseller

| Inspection Details Cont'd | |
|---------------------------------|--|
| Deluxe Instrumentation | None |
| Keyless Start | None |
| Visual Inspection | Clean |
| Operations Test | Failed Operations Test |
| Front Roller Condition | Good Condition |
| Front Roller Thickness | 1" |
| Front Roller Diameter | 55" |
| Front Roller Width | 78" |
| Rear Roller Condition | Good Condition |
| Rear Roller Thickness | 1/2" |
| Rear Roller Diameter | 54" |
| Rear Roller Width | 77" |
| Front and Rear Depth Percentage | Above 50% |
| Seat | Good Condition |
| Tailgate Lights | Non Operational |
| Working Lights | Non Operational |
| ROPS Condition | Good Condition |
| Engine Door | Good Condition |
| Intake Screen | Good Condition |
| Articulation Cylinder | Good Condition |
| Interior Condition | Good |
| Engine Compartment | Clean |
| Customer Decals Visible on Unit | None |
| Comments | The site would not operate the machine due to the warning code that appeared when the machine was on. The site indicated that it may be low on water. The front working lights and rear left working light are non operational. The rear tailgate light and left blinking light are non operational. |

Inspection Details Cont'd