

RECONDITIONING


RECONDITIONING NEEDED

ITEM	LABOR QTY	LABOR HOURS	PART COST	TOTAL COST
Clean and Detail	1	0	\$500.00	\$500.00
8 Drive Tires	1	0	\$4,000.00	\$4000.00
Refinish Hood	1	0	\$500.00	\$500.00
Refinish Bumper	1	0	\$400.00	\$400.00
Refinish Left Sleeper Side	1	0	\$400.00	\$400.00
Refinish Right Sleeper Side	1	0	\$400.00	\$400.00
Refinish Air Shield	1	0	\$600.00	\$600.00
Check Engine On- Open	1	0	\$2,500.00	\$2500.00
Labor (OHrs @ \$70.00):				\$0.00
Parts:				\$9,300.00
Total Recon Needed:				\$9,300.00

RECONDITIONING DATA ENTRY COMPLETE

NOTE: Reconditioning fees that require labor are based on a \$70.00 per hour labor rate.

TIRES



R: Recap NR: New Recap V: Virgin NV: New Virgin

NOTE: Actual brake percentage may vary from manufacturer to manufacturer. Measurements based on 16/32 new on front axles and 24/32 new on other axles.

COMMENTS

Creditor Comments:
Engine Hours: 15040

Public Comments:
Engine Hours: 15040

Starts/Runs: Yes

VALUE

Matrix Value: \$0.00

Retail Value: \$0.00

Appraisal Information:

This Unit was appraised by: [David Routhier](#) at IronPlanet on 12/23/2019. Phone: 418-569-3235.





