



DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR QUICK CHECK INSPECTION

CLIENT
 504 - Wells Fargo MSG
 INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER
 09/08/2020 | | FT095162 |

INSPECTOR: 5750
INSPECTION ID
 125081

Year, Make:	2015, JOHN DEERE	Full VIN:	1TC250BGAF095162
Model:	2500B	Engine Make:	JOHN DEERE
Engine Model:		Clean air idle:	
Classification:			

Note and photograph any body damage including scrapes, dents and glass:
 NONE

Note and photograph any major oil or fluid leaks:
 NONE

Note and photograph any damage including abnormal wear, holes, tears and waffling in trailer walls.
 NONE

Note any unusual engine noises or knocks:
 GOOD

List and photograph any tires with uneven wear:
 GOOD

Additional Comments:

Additional Services	Requested	Status	Comments
---------------------	-----------	--------	----------

ITEMS	COMMENTS
HOUR METER NOT WORKING	



DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR QUICK CHECK INSPECTION

CLIENT
504 - Wells Fargo MSG
INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER
09/08/2020 | | FT095162 |

INSPECTOR: 5750
INSPECTION ID
125081



ADDITIONAL 10



2



ADDITIONAL 6



ADDITIONAL 11



ADDITIONAL 1



ADDITIONAL 5



ADDITIONAL 9



SEAT



1



ADDITIONAL 4



ADDITIONAL 3



3



4



ADDITIONAL 2



ADDITIONAL 7



ADDITIONAL 8