


2021 VERMEER SC552

UNIT: 1VR9132UCM1001073

[Download Reconditioning Printout](#)







UNIT SPECS

Customer Wells Fargo (IMS)

LOCATION

Wells Fargo (IMS) 
Please call Pickup Support for location information
Davenport, FL 33897

GENERAL APPEARANCE

UID
1VR9132UCM1001073

Year
2021

Make
Vermeer

Model

SC552



Serial Number / VIN

1VR9132UCM1001073



Pre-Operational Checks

Confirm Fluids Checked: Engine Coolant. Confirm Fluids Checked: Engine(s) Oil. Confirm Fluids Checked: Hydraulic Fluid. Confirm Fluids Checked: Fuel Level. N/A: Transmission Fluid



Cab/Canopy Overhead Structural Framework

Bent metal



Condition

Overall Condition for Age:, Fair



SAFETY

Current Safety Manual

No



Current Operator/Maintenance Manual

Yes



Safety Lock Out/Stop

Operational



CONTROL STATION

Engine Oil Pressure

The gauge registers in the operating range.



Limited Function Check (Control Station)

The main components are in place and operational as noted.



Gauges

Operational



Hour Meter (Pre-inspection)

653 hrs



Hour Meter
654 hrs, Operational hour meter



Drivetrain
Hydrostatic Drive



Control Station
open



ENGINE

Starter
Operational



Fuel System
Operational



Oil Leaks
No dripping leaks



Limited Function Check (Engine)
The engine started and ran.



Radiator
Rating:
Good



Fuel Leaks
No dripping leaks



Cooling System Leaks
No dripping leaks



Emissions Status
2018 US EPA Label



Engine
Kohler 3 Cylinder 1.86 L Diesel Engine



HYDRAULICS

Valves

Rating:

Good



Hydraulic Tank

Rating:

Good



Limited Function Check (Hydraulics)

The hydraulic system was operational.



Pumps (Hydraulics)

Rating:

Good



Hydraulic Motors

Rating:

Good



Bar Lift Cylinders

Rating:

Good



Blade Cylinders

Rating:

Good



CHASSIS

Bar Pivot Point

Rating:

Good



Holders And Cutting Bits

Rating:

Good



Limited Function Check (Chassis)

The main chassis components were operational in a limited check.



Features

24 in Grinding Wheel



DRIVETRAIN

Transmission Type

Hydrostatic



Drive Motors

Rating:

Good



Final Drives

Rating:

Good



Limited Function Check (Drivetrain)

The drivetrain was operational.



RECONDITIONING

Cab/Canopy Overhead Structural Framework - Bent Metal

\$750

Total

\$750