Sprayer 051019

S/N: AGCA1300THNS	N1029		Year:	2017	Inspection Date: 031821		
Make: Rogator			Model:	RG1300B	Inspector: GMelton		
Location: Alliance AG Equip	ipment					Customer: Wells Fargo	
City: Troy			State:	TN	Hours: 1182		
1. General Appearance							
	Very Good	Good	Fair	Poor	N/A	Comments:	
Paint							
Sheet Metal Fiberglass							
Grab Irons							
Steps/Ladders							
Cab/ROPS							
Engine Enclosure/Hood							
Stack/Exhaust Pipe							
Radiator Grille/Shroud							
Fuel Tank							
Pre-Cleaner Bowl							
Battery Box						Jump post damaged	
Main Frame							
Boom Length	Na						
Boom							
Tank Size	Na						
Tank Type	Stainless	3					
Nozzles (#)	Na						
Nozzle Spacing	Na						
Nozzle Type	Na						
Comments/Recon:	1						
Chassis air bags do not inflat	e						

2. Operator Station (Cont'd)								

	Very Good	Good	Fair	Poor	N/A	Comments:
Dash/Console						
Switches						•
Interior Lights						•
EMS Panel/Warning Lights						<u></u>
Floorboards						•
Seat Cushion						-
Armrests						-
Doors						-
Door Latches						<u>-</u>
Windows						-
Mirror						2 glasses broken out
Air Conditioner						-
Heater						-
Windshield Wipers						-
Horn						<u>-</u>
Backup Alarm						-
Seat Belt						-
	Yes	No			,	
Manuals?						
Comments/Recon:	,	7				

3. Engine/Cooling/Electrical Systems

Engine Make/Model	Agco						
Serial Number	Cannot	read tag					
	Yes	No					
Blow By?							
Leaks?			At air co	ompressor			
Excessive Smoke?							
	Very Good	Good	Fair	Poor	N/A	Comments:	
Turbocharger							
Intake							
Exhaust Muffler							
Air Cleaner							
Fuel Injection System							
Governor							
Belts/Pulleys							
Engine Supports							
Water Pump							
Fan							
Fan Drive							
Radiator							
Coolers						Damaged	
Hoses							
Batteries/Cables							
Starter							
Alternator							
Pre Heater							
Exterior Lights						2 inop	
Wiring							
Engine Operating Condition							
	Yes	No					
Starts/Runs?							
Comments/Recon:							

Page 3

4. Steering/Brakes						
	Very Good	Good	Fair	Poor	N/A	Comments:
Right Turn Operation			٥		٥	
Left Turn Operation						
Lines/Hoses						
Comments/Recon:		,	,		,	
5. Hydraulics						
	Very Good	Good	Fair	Poor	N/A	Comments:
Operating Condition						
Controls/Lever						
Tank						
Pumps/Valves						
Hoses/Lines			٥			
	Yes	No		7	-	
Leaks?			At cool	er		
	Very Good	Good	Fair	Poor	N/A	Comments:
Cylinders						
Comments/Recon:					2	

	Very Good	Good	Fair	Poor	N/A	Comments:		
rward Operation								
everse Operation								
verall Operation								
ght Side Wheel Motor								
eft Side Wheel Motor								
nes						Corrosion at connections		
omments/Recon:	<u> </u>	,	•	•	,			
. Tires								
. 11103								
	Left	Front				Right Front		
Make/		ICH AYBIB			MICH SPRAYBIB			
Model								
Size	VF380/90R46				VF380/90R46			
Tread	18/32					41/32		
Depth								
Cuts/	Tread separation					No		
Gouges?	Yes					No		
Recaps?	·	6 5				INO		
	Left	Rear			Right Rear			
Make/		ICH AVBIB			MICH			
Model		AYBIB			SPRAYBIB			
Size	VF380)/90R46				VF380/90R46		
Tread	34	l/32				41/32		
Depth								
Cuts/	1	No				No		
Gouges?		I-				NI.		
Recaps?	Γ	No				No		
omments/Recon:								

8. Attachments							
Auto Guidance Components	Monitor	Antenna	Controller				
Make	Raven	Raven					
Model	Na	Na					
Serial Number	000001092	14329					
Comments/Recon:	· Raven- 21638		1				
Light bar-	Traven- 21030						
	1st	2nd	3rd				
Make							
Model							
General Description							
Serial Number							
Operating Condition							
Cylinder							
Pins/Bushings							
Lines/Hoses							
Pump/Motor							
Controls							
Hi Flow/Standard Flow							
Electrical Connection							
Comments/Recon:	Comments/Recon:						

2017 AGCO ROGATOR SPRAYER RG1300B

UNIT: AGCA1300THNSN1029

Price: \$0.00 USD View Asset




































































IDENTIFICATIO	N		
S/N	AGCA1300THNSN1029	Year	2017
Make	AGCO RoGator Sprayer	Model	RG1300B
Hours	1182		
GENERAL APPE	EARANCE		
Paint	Good	Sheet Metal/Fiberglass	Good
Grab Irons	Good	Steps/Ladder	Good
Cab/ROPS	Good	Engine Enclosure/Hood	Good
Stack	Good	Radiator Grille	Good
Fuel Tank	Good	Precleaner Bowl	Good
Battery Box	Fair	Main Frame	Good
Boom	N/A	Tank Type	Stainless
OPERATOR STA	ATION		
Dash/Console	Good	Switches	Good
Interior Lights	Good	EMS Panel/Warning Lights	Good
Floor Boards	Good	Seat Cushion	Good
Arm Rests	Good	Doors	Good
Door Latches	Good	Windows	Good
	Poor	Air Conditioner	Good
Mirrors	1 001		
Mirrors Heater	Good	Windshield Wipers	Good

Seat Belt	Good	Manuals?	Yes
ENGINE/COOLING/ELECTRI	CAL SYSTE	MS	
Engine Make	Agco	Blow By?	No
Oil Leaks?	Yes	Excessive Smoke?	No
Turbocharger	Good	Intake	Good
Exhaust/Muffler/Stack	Good	Air Cleaner	Good
Fuel Injection System	Good	Governor	Good
Belts/Pulleys	Good	Engine Supports	Good
Water Pump	Good	Fan	Good
Fan Drive	Good	Radiator	Good
Coolers	Fair	Hoses	Good
Batteries/Cables	Good	Starter	Good
Alternator	Good	Pre-Heater	Good
Exterior Lights	Fair	Wiring	Good
Engine Operation	Good	Starts/Runs?	Yes
STEERING/BRAKES			
Right Turn Operation	Good	Left Turn Operation	Good
Steering Lines/Hoses	Good		
HYDRAULICS			
Hydraulic Operation	Good	Controls/Levers	Good
Tank	Good	Pumps/Valves	Good
Lines/Hoses	Good	Hydraulic Leaks?	Yes
Cylinders	Good		
HYDROSTATIC DRIVE			
Forward Operation	Good	Reverse Operation	Good
Overall Operation	Good	Right Side Wheel Motor	Good

eft Side Wheel Motor	Good	Lines	Fai
TIRES			
eft Front Make	Michelin	Left Front Size	VF380/90R46
eft Front Tread Depth	18/32	Right Front Make	Michelin
tight Front Size	VF380/90R46	Right Front Tread Depth	41/32
eft Rear Make	Michelin	Left Rear Size	VF380/90R46
eft Rear Tread Depth	34/32	Right Rear Make	Michelii
light Rear Size	VF380/90R46	Right Rear Tread Depth	41/32
ntenna Make	Raven	Antenna Serial Number	14329





■ SN1029.pdf

UNIT SPECS

Customer	Wells Fargo	S/N	AGCA1300THNSN1029
Year	2017	Make	AGCO RoGator Sprayer
Model	RG1300B	Hours	1182

INSPECTION LOCATION



ALLIANCE AG EQUIPMENT LLC Troy, TN 38260 866-518-4976

CURRENT LOCATION



ALLIANCE AG EQUIPMENT LLC Troy, TN 38260 866-518-4976

VERSION HISTORY ②

