



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

**TRACTOR QUICK CHECK INSPECTION**

**INSPECTOR: 5750**  
**INSPECTION ID**  
**117874**

**CLIENT**  
 504 - Wells Fargo MSG  
**INSP DATE** | **FLEET NAME** | **VIN (LAST 8)** | **PO NUMBER**  
 05/19/2020 | | FM050422 |

|  |                  |                        |                   |
|--|------------------|------------------------|-------------------|
| <b>Year, Make:</b>   | 2015, JOHN DEERE | <b>Full VIN:</b>       | 1M0220SACFM050422 |
| <b>Model:</b>  | 220SA            | <b>Engine Make:</b>    | JOHN DEERE        |
| <b>Engine Model:</b>   |                  | <b>Clean air idle:</b> |                   |
| <b>Classification:</b>   | Utility vehicle  |                        |                   |
| <b>Note and photograph any body damage including scrapes, dents and glass:</b>                             |                  |                        |                   |
| NONE   |                  |                        |                   |
| <b>Note and photograph any major oil or fluid leaks:</b>   |                  |                        |                   |
| NONE   |                  |                        |                   |
| <b>Note and photograph any damage including abnormal wear, holes, tears and waffling in trailer walls.</b> |                  |                        |                   |
| NONE   |                  |                        |                   |
| <b>Note any unusual engine noises or knocks:</b>   |                  |                        |                   |
| NONE   |                  |                        |                   |
| <b>List and photograph any tires with uneven wear:</b>   |                  |                        |                   |
| WORN UNDER 50%   |                  |                        |                   |
| <b>Additional Comments:</b>  |                  |                        |                   |
|  |                  |                        |                   |

| Additional Services | Requested | Status | Comments |
|---------------------|-----------|--------|----------|
|---------------------|-----------|--------|----------|

| ITEMS                         | COMMENTS |
|-------------------------------|----------|
| TIRES WORN UNDER 50%          |          |
| NO VIN TAG UNIT # TO IDENTIFY |          |



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

**TRACTOR QUICK CHECK INSPECTION**

CLIENT  
 504 - Wells Fargo MSG  
 INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER  
 05/19/2020 | | FM050422 |

INSPECTOR: 5750  
 INSPECTION ID  
 117874



LEFT REAR



RIGHT REAR



ENGINE



ENGINE TAG



ENGINE



TIRE



ADDITIONAL 5



ADDITIONAL 12



ADDITIONAL 18



ADDITIONAL 1



ADDITIONAL 2



ADDITIONAL 4



ADDITIONAL 7



ADDITIONAL 8



ADDITIONAL 9



ADDITIONAL 10



DEKRA Services Inc.  
Customer Service 770-257-0107

### TRACTOR QUICK CHECK INSPECTION

CLIENT  
504 - Wells Fargo MSG  
INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER  
05/19/2020 | | FM050422 |

INSPECTOR: 5750  
INSPECTION ID  
117874



ADDITIONAL 11



ADDITIONAL 13



ADDITIONAL 14



ADDITIONAL 15



ADDITIONAL 16



ADDITIONAL 17



ADDITIONAL 19