



Aspen Field Services

Job #: 23926 /

Serial #: 70C6-5652

For more information, visit:

wellsfargo.com/equipmentseller

2016 KAWASAKI 70Z7



Video:



PHOTOS: Click the link below to view all high resolution images

https://app.staging.aspenfieldservices.com/api/attachments/get/3ddKjuM5CibYsqPLf/report_0023926_3ddKjuM5CibYsqPLf.pdf

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Master Lease Number	001-0496597-100
Year	2016
Make	KAWASAKI
Model	70Z7
Serial Number	70C6-5652
Type	Wheel Loader
Inspection Date	8/26/2020
Location of Business	13301 Great Coastal Dr , Chester, VA, 23836, USA
Attachment(s)/ Accessory(s)	Roll-Out Bucket Serial Number 0616-AKR42554
Enclosed Cab	Yes
Engine MFR	Not Visible
Controls	Standard
Hours	4136
Cab A-C	Yes
Cab Heat	Yes



Aspen Field Services

Job #: 23926 /

Serial #: 70C6-5652

For more information, visit:

wellsfargo.com/equipmentseller

2016 KAWASAKI 70Z7

Inspection Details Cont'd	
Backup Camera	No
Deluxe Instrumentation	Yes
Keyless Start	No
Visual Inspection	Clean
Operational Test	Operational
Front Right Tire Part Number	Bridgestone: F5M182611
Front Right Tire Depth Percentage	Above 50%
Front Right Tire Condition	Cut
Front Right Tire Depth Measurement	Above 50%
Front Left Tire Part Number	Bridgestone: F5M182611
Front Left Tire Depth Percentage	Below 50%
Front Left Tire Condition	Good Condition
Front Left Tire Depth Measurement	Below 50%
Back Right Tire Part Number	Bridgestone: F5M182611
Back Right Tire Depth Percentage	Below 50%
Back Right Tire Condition	Cut
Back Right Tire Depth Measurement	Below 50%
Back Left Tire Part Number	Bridgestone: F5M182611
Back Left Tire Depth Percentage	Below 50%
Back Left Tire Condition	Cut
Back Left Tire Depth Measurement	Below 50%
Mismatched Tires	No
Tilt Cylinders	No Leaks
Lift Cylinders	No Leaks
Boom Arms Operations	Operational
Seat	Good Condition
Tailgate Lights	Good Condition
Working Lights	Good Condition
Front Door	Good Condition
Side Glass Complete	Good Condition
Boom Arms Damages	None
Rear Door	Good Condition
Mufflers	Good Condition
ROPS Condition	Good Condition
Articulational Cylinders	No Leaks
Cab A-C Condition	Operational
Cab Heat Condition	Operational
Intake Screen	Good Condition
Interior	Good Condition

Inspection Details Cont'd	
Engine Compartment	Dirty
Customer Decals Visible on Unit	None
Comments	