



Video:



PHOTOS: Click the link below to view all high resolution images

https://app.aspenfieldservices.com/api/attachments/get/ogW4GpiyfuuNggqNK/full_report_0030888_ogW4GpiyfuuNggqNK.pdf?view

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	2018
Make	Vogele
Model	Super 1300-3i
Serial Number	14110117
Type	Paver
Date Of Inspection	5/28/2021
Location of Inspection	JJ Kane Auctioneers; 2841 Verona Mudlick Rd, Suite B, Verona, KY 41092
Attachment(s)/ Accessory(s)	None
Engine MFR	Not Visible
Controls	Standard
Hours	392
Visual Inspection	Clean
Operational Test	Passed - Operational
Left Track Condition	Good Condition
Left Track Brand	Vogele



Aspen Field Services

Job #: 30888 /

Serial #: 14110117

For more information, visit:

wellsfargo.com/equipmentseller

2018 VOGELE SUPER 1300-3I ASPHALT
PAVER

Inspection Details Cont'd	
Left Track Tread Depth Measurement	2"
Left Track Tread Depth Percentage	Above 75%
Left Track Sprocket	Good Condition
Left Track Rollers	Good Condition
Left Track Idler	Good Condition
Right Track Condition	Good Condition
Right Track Brand	Vogele
Right Track Tread Depth Measurement	2"
Right Track Tread Depth Percentage	Above 75%
Right Track Sprocket	Good Condition
Right Track Rollers	Good Condition
Right Track Idlers	Good Condition
Mismatched Tracks	No
Material Hoppers Operations	Operational
Operator Seat	Good Condition
Passenger Seat	Good Condition
Engine Door	Opens and Closes
Engine Compartment	Clean
Mufflers	Good Condition
Intake Screen	Good Condition
Customer Decals Visible on Unit	Yes
Working Lights	Good Condition
Rear Working Lights	Good Condition
Mirrors	Good Condition
Comments	

Inspection Details Cont'd