



DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR QUICK CHECK INSPECTION

CLIENT
 504 - Wells Fargo MSG
 INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER
 05/19/2020 | | FT095217 |

INSPECTOR: 5750
 INSPECTION ID
 117862

Year, Make:	2015, JOHN DEERE	Full VIN:	1TC250BGFT095217
Model:	2500B	Engine Make:	JOHN DEERE
Engine Model:		Clean air idle:	
Classification:	Utility vehicle		

Note and photograph any body damage including scrapes, dents and glass:
 GOOD

Note and photograph any major oil or fluid leaks:
 GOOD

Note and photograph any damage including abnormal wear, holes, tears and waffling in trailer walls.
 GOOD

Note any unusual engine noises or knocks:
 GOOD

List and photograph any tires with uneven wear:

Additional Comments:

Additional Services	Requested	Status	Comments
---------------------	-----------	--------	----------

ITEMS	COMMENTS
HOURMETER 2452	



DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR QUICK CHECK INSPECTION

CLIENT
 504 - Wells Fargo MSG
 INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER
 05/19/2020 | | FT095217 |

INSPECTOR: 5750
 INSPECTION ID
 117862



FRONT RIGHT



VIN



FRONT LET



FRONT



RIGHT REAR



LEFT REAR



HOURL METER



ADDITIONAL 11



ADDITIONAL 9



ENGINE



ADDITIONAL 8



TIRE



ADDITIONAL 7



ADDITIONAL 1



ADDITIONAL 6



ADDITIONAL 10