



Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance		
Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	VBP00021007006750	 <p>POTTINGER Alle Pottinger Maschinenbau GmbH AT-2712 Gleisdorf Chassis no. 38110002735 Model NOVACAT 351 alpha-motion Type 3811 Tare Weight 995 kg Serial no. VBP00021007006750 Made in Austria www.pottinger.at/potlpro 30-EN www.IronPlanet.com U543749 IRON PLANET</p>
CE Mark	No CE mark found	
v2 General Appearance # 1		 <p>NOVACAT 351 U543749 IRON PLANET</p>
v2 General Appearance # 2		 <p>IRON PLANET</p>
v2 General Appearance # 3		 <p>IRON PLANET</p>
v2 General Appearance # 4		 <p>IRON PLANET</p>
v2 General Appearance # 5		 <p>IRON PLANET</p>
v2 General Appearance # 6		 <p>IRON PLANET</p>

v2 General Appearance # 7		
v2 General Appearance # 8		

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet , Inc. © 2012 All Rights Reserved