

Job #: 25597 / Serial #: 86860 For more information, visit: wellsfargo.com/equipmentseller









Video:



PHOTOS: Click the link below to view all high resolution images

https://app.staging.aspenfieldservices.com/api/attachments/get/
MzQ5MCFbTbfpACQK2/full_report_0025597_MzQ5MCFbTbfpACQK2.pdf?
view

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	2017
Make	McCloskey
Model	S190
Serial Number	86860
Туре	High Prod Screener
Inspection Date	12/3/2020
Location of Inspection	JJ Kane Auctioneers - Rome; 5835 Success Dr, Rome, NY 13440
Engine Compartment	Dirty
Engine MFR	Caterpillar
Hours	4318
Hydraulic Lines	No Leaks
Hydraulic Cylinders	No Leaks
Left Track Condition	Good Condition
Left Track Depth Percentage	NA Metal Tracks
Left Track Idler	Good Condition

Emergency

Stop

Feed Conveyor

Main Conveyor

Tail Conveyor Yes

48"

42"

48"

Aspen Field Services

Job #: 25597 / Serial #: 86860

For more information, visit: wellsfargo.com/equipmentseller

Inspection Details Cont'd **Good Condition** Left Track Sprocket Left Track **Good Condition** Rollers Right Track **Good Condition** Condition Right Track NA Metal Tracks Depth Percentage Right Track **Good Condition** Idler Right Track **Good Condition** Sprocket Right Track **Good Condition** Rollers Hopper 12' Hopper 10.5 Cubic Yards Capacity **Platforms Good Condition Body Paint** Minor Rust Visual Clean Inspection Landing **Good Condition** Gear 5' x 20' Screener Side Two Converyors Diesel Fuel Horse Power 125 HP Steps / **Good Condition** Ladders Weight 79,400 Lbs Transport 11 ft. 2in. Height **Transport** 56 ft. 7 in. Length Transport 9 ft. 6 in. Width Conveyor **Good Condition** Belts **Good Condition Belt Rollers** Controls Standard Diesel Tank 105 Gallons Hydraulic 166 Gallons Tank

Inspection Details Cont'd



Aspen Field Services Job #: 25597 /

Job #: 25597 / Serial #: 86860

For more information, visit: wellsfargo.com/equipmentseller

2017 MCCLOSKEY S1903DT HIGH PROD. SCREENER

Side Conveyor	32"
Active Warnings	None
Operational	Yes
Comments	The serial number plate is missing from the machine, preventing us from verifying the serial number of the unit. The screener is in overall good condition. The tracks, rollers, sprockets, and idlers are in good condition. The belts and rollers are good as well. The body of the unit is in fair condition showing little wear and tear. The engine starts and runs smoothly and there are no visible signs of leaks or issues. The battery box is fairly dirty but the connection is still good and there were no issues in operating the equipment. The hydraulic engine, cylinders, and hoses show no signs of leakage.