



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

### TRACTOR QUICK CHECK INSPECTION

CLIENT

504 - Wells Fargo MSG

INSP DATE

09/08/2020

FLEET NAME

VIN (LAST 8)

FR020147

PO NUMBER

INSPECTOR: 5750

INSPECTION ID

125084

<b>Year, Make:</b>	2015, JOHN DEERE	<b>Full VIN:</b>	1TC870AVPFR020147
<b>Model:</b>	8700A	<b>Engine Make:</b>	JOHN DEERE
<b>Engine Model:</b>		<b>Clean air idle:</b>	
<b>Classification:</b>			
<b>Note and photograph any body damage including scrapes, dents and glass:</b>			
NONE			
<b>Note and photograph any major oil or fluid leaks:</b>			
NONE			
<b>Note and photograph any damage including abnormal wear, holes, tears and waffling in trailer walls.</b>			
NONE			
<b>Note any unusual engine noises or knocks:</b>			
GOOD			
<b>List and photograph any tires with uneven wear:</b>			
DRIVE TIRES WORN			
<b>Additional Comments:</b>			

Additional Services	Requested	Status	Comments
---------------------	-----------	--------	----------

ITEMS	COMMENTS
HOURS 1529	
DRIVE TIRES WORN	



DEKRA Services Inc.  
Customer Service 770-257-0107

TRACTOR QUICK CHECK INSPECTION

CLIENT 504 - Wells Fargo MSG			
INSP DATE 09/08/2020	FLEET NAME	VIN (LAST 8) FR020147	PO NUMBER

INSPECTOR: 5750  
INSPECTION ID  
125084



VIN



RIGHT REAR



LEFT FRONT



FRONT



1



2



ADDITIONAL 13



ADDITIONAL 14



ADDITIONAL 9



TIRES



ADDITIONAL 2



ADDITIONAL 6



ENGINE TAG



ENGINE



ADDITIONAL 1



ADDITIONAL 3



**DEKRA Services Inc.**  
**Customer Service 770-257-0107**

**TRACTOR QUICK CHECK INSPECTION**

CLIENT  
504 - Wells Fargo MSG  
INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER  
09/08/2020 | | FR020147 |

INSPECTOR: 5750  
INSPECTION ID  
125084



ADDITIONAL 5



ADDITIONAL 7



ADDITIONAL 10



ADDITIONAL 11



ADDITIONAL 12