



## Item #8372407 - Great Plains 3P YPA Split 12 Row No-Till Planter



### Item Details:

- Features: 3-Point Hitch, 22 in Spacing
- Meter Reading: Not Available
- Serial # : GP-B1143J
- Inspection Completed: 11/17/22





### Shipping Details:








- Location Louisiana (Catahoula County)
- Loading Dock Available: No
- Pickup Hours: -

# Inspection Report

**Note:** This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.








Inspection Ratings Key	
★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance		
Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	GP-B1143J	
Hour Meter / Odometer	0 Not Available	
v2 General Appearance # 1		
v2 General Appearance # 2		
v2 General Appearance # 3		
v2 General Appearance # 4		
v2 General Appearance # 5		
v2 General Appearance # 6		

v2 General Appearance # 7		 A close-up photograph of the green metal frame and components of a planter, showing various mechanical parts and hydraulic lines.
v2 General Appearance # 8		 A photograph showing the row units of the planter, which include multiple sets of disc and chisel blades mounted on a frame.
v2 General Appearance # 9		 A photograph of a large, black, treaded tire mounted on a metal axle, part of the planter's chassis.
v2 General Appearance # 10		 A close-up photograph of a large, circular disc component, likely a disc blade, mounted on the planter's frame.
v2 General Appearance # 11		 A photograph showing the row units of the planter from a different angle, highlighting the disc and chisel blades.
v2 General Appearance # 12		 A photograph of the main frame of the planter, showing the complex arrangement of metal beams and components.
v2 General Appearance # 13		 A photograph showing the row units of the planter, focusing on the disc and chisel blades.



v2 General Appearance # 14		
v2 General Appearance # 15		
v2 General Appearance # 16		
v2 General Appearance # 17		
v2 General Appearance # 18		
v2 General Appearance # 19		
v2 General Appearance # 20		

v2 General Appearance # 21



IronPlanet , Inc. © 2012 All Rights Reserved