

# CONSTRUCTION EQUIPMENT CONDITION REPORT

For more information, visit:  
wellsfargo.com/equipseller



**Commerical Vehicle Inspection Group**  
Truck, Tractor, Trailer, and Equipment  
Inspections throughout North America  
203-628-4325 info@cvigna.com

Make:	Komatsu	Type:	DOZER	Inspector:	GP
Model:	D51PXi24	Hours:	6147	Inspection Date:	8/30/2024
SN:	KMT0D133CKA10767	Year:	2019		

## SPECIFICATIONS

<b>Tracks</b>	Tracks Model:	<b>SINGLE GROUSER</b>	Cut:	<b>No</b>	Controls:	<b>FWD - REV - LEFT - RIGHT - RAISE / LOWER CUTTER</b>
	Tread Depth:	<b>52/32</b>	Tread %:	<b>Over 50%</b>		
Enclosed Cab:	<b>Yes</b>	Heat:	<b>Yes</b>	A/C:	<b>Yes</b>	
Bucket Width:	<b>132</b>	Teeth:	<b>Without</b>	Damaged:	<b>No</b>	
Other Options:	<b>BLADE TILTS AND SWINGS LEFT TO RIGHT</b>					

## CONDITION REPORT

Check	Comments / Deficiencies
✓ Frame	
N/A Boom & Uprights	
✓ Lift Cylinders	
✓ Tilt Cylinders	
✓ R H Drive	QUIET
✓ L H Drive	QUIET
✓ Variable Speed	QUIET
✓ Engine	QUIET
✓ Appearance	GOOD
N/A Describe Missing Parts	
✓ Attachment Inspection	
X Condition Report	GROUSER PADS WORN ON EDGE

PHOTOS



Front Left



PHOTOS



Front Right



Rear

PHOTOS



PHOTOS



Seating / Interior

PHOTOS



PHOTOS



PHOTOS

