

# BOBCAT EQUIPMENT CONDITION REPORT

For more information, visit:  
wellsfargo.com/equipmentseller



**Commerical Vehicle Inspection Group**  
Truck, Tractor, Trailer, and Equipment  
Inspections throughout North America  
203-628-4325 info@cvigna.com

Make:	Bobcat	Type:	Skid Steer	Inspector:	WW
Model:	S66	Hours:	826	Inspection Date:	1/3/2025
SN:	B4SA13235	Year:	2021		

## SPECIFICATIONS

ROPS:	<b>Yes</b>	Hours:	<b>826</b>			
Enclosed Cab:	<b>Yes</b>	Cab Heat:	<b>Yes</b>	Cab A/C:	<b>Yes</b>	Controls: <b>Standard</b>
Attachment on Machine:	74" Bucket					
Additional Attachments:	N/A					
2-Speed:	<b>Yes</b>	Engine MFR:	<b>DOOSAN</b>	Tires		
High Flow Hydraulics - Sticker:	<b>No</b>	Power Bob-Tach:	<b>Yes</b>	Keyless Start:	<b>Yes</b>	
Backup Camera:	<b>No</b>	Ride Control:	<b>Yes</b>	Deluxe Instrumentation:	<b>Yes</b>	
Hydraulic X-Change:	<b>No</b>					
Comments and Defects:	<b>N/A,</b>					

# BOBCAT EQUIPMENT CONDITION REPORT

For more information, visit:  
wellsfargo.com/equipseller



**Commerical Vehicle Inspection Group**  
Truck, Tractor, Trailer, and Equipment  
Inspections throughout North America  
203-628-4325 info@cvigna.com

Tire Fault Legend			
C - Cut	D - Dry	F - Flat	M - Mismatched Tread / Casings
WD - Wheel Damage			

FRONT AXLE		
Make: BOBCAT Part #: 0 Measure: 14 / 32 Condition: FAIR Tread Remaining: Over 50% Fault:		Make: BOBCAT Part #: 0 Measure: 14 / 32 Condition: FAIR Tread Remaining: Over 50% Fault:

REAR AXLE		
Make: BOBCAT Part #: 0 Measure: 13 / 32 Condition: POOR Tread Remaining: Over 50% Fault: F		Make: BOBCAT Part #: 0 Measure: 14 / 32 Condition: FAIR Tread Remaining: Over 50% Fault:

# BOBCAT EQUIPMENT CONDITION REPORT

For more information, visit:  
wellsfargo.com/equipseller



**Commerical Vehicle Inspection Group**  
Truck, Tractor, Trailer, and Equipment  
Inspections throughout North America  
203-628-4325 info@cigna.com

## CONDITION REPORT

Check	Comments / Deficiencies
✓ Visual Inspection	CLEAN
✓ Operational Test	PASSED - MOVED FORWARD/BACK WARD - LIFTED UP AND DOWN
✓ Lift Cylinders	NO LEAKS
✓ Tilt Cylinders	NO LEAKS
✓ Boom Arms Operations	WORKING
✓ Seat	GOOD CONDITION
✓ Tailgate Lights	GOOD CONDITION
✓ Working Lights	GOOD CONDITION
✓ Front Door	NO DAMAGES
✓ Rear and Top Window	NO DAMAGES
✓ Side Glass Complete	NO DAMAGES
✓ Boom Arms Damages	NO DAMAGES
✓ Rear Door	OPENS AND CLOSES AND STAYS CLOSED
✓ Mufflers	GOOD CONDITION
✓ ROPS Condition	GOOD CONDITION
✓ Power Bob-Tach Condition	OPERATIONAL
✓ Cab A-C Condition	WORKING
✓ Cab Heat Condition	WORKING
✓ Intake Screen	GOOD CONDITION
✓ Eng. Compartment	
N/A Hydraulic X-Change Condition	
✓ Customer Decals Visible on Unit	NO
✓ Error Codes	
X Rear Left Tire Faults	TIRE IS FLAT

PHOTOS



Seating / Interior





PHOTOS



PHOTOS





PHOTOS





PHOTOS



Front Right



Rear



PHOTOS



Front Left





PHOTOS





PHOTOS





PHOTOS





PHOTOS





PHOTOS

