

# BOBCAT EQUIPMENT CONDITION REPORT

For more information, visit:  
wellsfargo.com/equipseller



**Commerical Vehicle Inspection Group**  
Truck, Tractor, Trailer, and Equipment  
Inspections throughout North America  
203-628-4325 info@cvig.com

Make:	Bobcat	Type:	Mini Excavator	Inspector:	CM
Model:	E20	Hours:	727	Inspection Date:	12/3/2024
SN:	B3BL21051	Year:	2022		

## SPECIFICATIONS

ROPS:	<b>Yes</b>	Hours:	<b>727</b>		
Enclosed Cab:	<b>No</b>	Cab Heat:	<b>No</b>	Cab A/C:	<b>No</b> Controls: <b>Standard</b>
Attachment on Machine:	12" Bucket				
Additional Attachments:	N/A				
2-Speed:	<b>Yes</b>	Engine MFR:	<b>KUBOTA</b>	<b>Tracks</b>	
High Flow Hydraulics - Sticker:	<b>No</b>	Power Bob-Tach:	<b>No</b>	Keyless Start:	<b>No</b>
Backup Camera:	<b>No</b>	Ride Control:	<b>No</b>	Deluxe Instrumentation:	<b>No</b>
Hydraulic X-Change:	<b>No</b>				
Comments and Defects:	<b>NONE,</b>				

# BOBCAT EQUIPMENT CONDITION REPORT

For more information, visit:  
wellsfargo.com/equipseller



**Commerical Vehicle Inspection Group**  
Truck, Tractor, Trailer, and Equipment  
Inspections throughout North America  
203-628-4325 info@cvigna.com

Tire Fault Legend			
C - Cut	D - Dry	F - Flat	M - Mismatched Tread / Casings
WD - Wheel Damage			

TRACKS		
Make: BOBCAT Part #: SP230X48X72 SIKF Measure: 22 / 32 Condition: GOOD Tread Remaining: Over 50% Fault:		Make: BOBCAT Part #: SP230X48X72 SIKF Measure: 22 / 32 Condition: GOOD Tread Remaining: Over 50% Fault:

# BOBCAT EQUIPMENT CONDITION REPORT

For more information, visit:  
wellsfargo.com/equipmentseller



**Commerical Vehicle Inspection Group**  
Truck, Tractor, Trailer, and Equipment  
Inspections throughout North America  
203-628-4325 info@cvigna.com

## CONDITION REPORT

Check	Comments / Deficiencies
✓ Visual Inspection	CLEAN
✓ Operational Test	PASSED - MOVED FORWARD/BACK WARD - LIFTED UP AND DOWN
✓ Lift Cylinders	NO LEAKS
✓ Tilt Cylinders	NO LEAKS
✓ Boom Arms Operations	WORKING
X Seat	CUT
✓ Tailgate Lights	GOOD CONDITION
X Working Lights	BENT HOUSING
N/A Front Door	
N/A Rear and Top Window	
N/A Side Glass Complete	
✓ Boom Arms Damages	NO DAMAGES
✓ Rear Door	OPENS AND CLOSES AND STAYS CLOSED
✓ Mufflers	GOOD CONDITION
✓ ROPS Condition	GOOD CONDITION
N/A Power Bob-Tach Condition	
N/A Cab A-C Condition	
N/A Cab Heat Condition	WORKING
✓ Intake Screen	GOOD CONDITION
✓ Eng. Compartment	
N/A Hydraulic X-Change Condition	
✓ Customer Decals Visible on Unit	NO
✓ Error Codes	

PHOTOS



Front Left



Front Right



PHOTOS



Rear



Seating / Interior



PHOTOS



PHOTOS



PHOTOS





PHOTOS



PHOTOS



PHOTOS



PHOTOS

