

CONSTRUCTION EQUIPMENT CONDITION REPORT

For more information, visit:
wellsfargo.com/equipseller



Commerical Vehicle Inspection Group
Truck, Tractor, Trailer, and Equipment
Inspections throughout North America
203-628-4325 info@cvigna.com

Make:	Komatsu	Type:	DOZER	Inspector:	GP
Model:	D51PXi 24	Hours:	6029	Inspection Date:	8/30/2024
SN:	KMT0D133JKBB20763	Year:	2019		

SPECIFICATIONS

Tracks	Tracks Model:	SINGLE GROUSER	Cut:	No	Controls:	FWD - REV - LEFT - RIGHT - RAISE / LOWER CUTTER
	Tread Depth:	62/32	Tread %:	Over 50%		
Enclosed Cab:	Yes	Heat:	Yes	A/C:	Yes	
Bucket Width:	132	Teeth:	Without	Damaged:	No	
Other Options:	11' BLADE - TILTS AND SWINGS SIDE TO SIDE REAR CAMERA					

CONDITION REPORT

Check	Comments / Deficiencies
✓ Frame	
✓ Boom & Uprights	
✓ Lift Cylinders	
✓ Tilt Cylinders	
✓ R H Drive	QUIET
✓ L H Drive	QUIET
✓ Variable Speed	QUIET
✓ Engine	QUIET
✓ Appearance	GOOD
N/A Describe Missing Parts	
✓ Attachment Inspection	

PHOTOS



Seating / Interior



Rear



Front Right



Front Left

PHOTOS



PHOTOS



PHOTOS



PHOTOS



PHOTOS

