



Video:



PHOTOS: Click the link below to view all high resolution images

[https://app.aspenfieldservices.com/api/attachments/get/tsyQmZNBjYoJgaBug/full\\_report\\_0034438\\_tsyQmZNBjYoJgaBug.pdf?view](https://app.aspenfieldservices.com/api/attachments/get/tsyQmZNBjYoJgaBug/full_report_0034438_tsyQmZNBjYoJgaBug.pdf?view)

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	2018
Make	Atlas
Model	V21 Stage IV
Type	Air Compressor
VIN	APP802689
Inspection Date	09/30/2021
Location of Business	JJ Kane Auctioneers - 1402 Conshohocken Rd, Plymouth Meeting, PA, 19462
Hours	NA - See Notes
Warning Lights	NA - See Notes
Operational Test	Not Operational
Body Paint	Good Condition
Engine Doors	Good Condition
Engine Compartments	Good Condition
Back Right Tire Condition	Good Condition
Back Right Tire Brand	Sailun



# Aspen Field Services

Job #: 34438 /

Serial #: APP802689

For more information, visit:

[wellsfargo.com/equipmentseller](http://wellsfargo.com/equipmentseller)

ATLAS COPCO COMPRESSOR V21

Inspection Details Cont'd	
Back Right Tire Size	215/75R17.5
Back Right Tire Tread Depth Measurement	16/32"
Back Right Tire Tread Depth Percentage	50%
Front Right Tire Condition	Good Condition
Front Right Tire Brand	Sailun
Front Right Tire Size	215/75R17.5
Front Right Tire Tread Depth Measurement	15/32"
Front Right Tire Tread Depth Percentage	47%
Back Left Tire Condition	Good Condition
Back Left Tire Brand	Sailun
Back Left Tire Size	215/75R17.5
Back Left Tire Tread Depth Measurement	15/32"
Back Left Tire Tread Depth Percentage	47%
Front Left Tire Condition	Good Condition
Front Left Tire Brand	Sailun
Front Left Tire Size	215/75R17.5
Front Left Tire Tread Depth Measurement	16/32"
Front Left Tire Tread Depth Percentage	50%
Comments	Equipment is not operational. The left front axle hub cap is missing.

Inspection Details Cont'd
---------------------------