

2019 K-TEC 1237

UNIT: KS03080

[Download Reconditioning Printout](#)






UNIT SPECS

Customer Wells Fargo (IMS)

LOCATION

Wells Fargo (IMS) 
Please call Pickup Support for location information
Davenport, FL 33897

GENERAL APPEARANCE

UID	KS03080	CE Mark	CE Marked
Make and Model Review	Hydraulic 4 Tire	General Condition	Good

CHASSIS

Belly pans Rating	Good	Suspension System	cushion ride valve missing
Suspension System Rating	Poor	Hitch Condition (Structural) Rating	Good
Draft Arm Condition Rating	Good	Draft Arm Trunnions Rating	Good
Bowl Condition Rating	Good	Ejector Face Condition Rating	Good
Apron Condition Rating	Good	Apron Trunnions Rating	Good
Push Block Rating	Good	Cutting Edges Rating	Good
Tire Size(s)	Position: Trail Scraper, Tire Size: 26.5R25 Tires		

LOGISTICS INFORMATION

General Shipping Information

Yes: Is the unit wider than 8'6"? Yes: Inflated Tires - item can roll? No: Does this Unit Run? No: If self propelled, does the unit travel? No: Is the unit taller than 12'? No: Noticeable fluid leaks?

RECONDITIONING

Suspension System - Cushion Ride Valve Missing

\$1,500



Total

\$1,500