

BOBCAT EQUIPMENT CONDITION REPORT

For more information, visit:
wellsfargo.com/equipseller



Commerical Vehicle Inspection Group
Truck, Tractor, Trailer, and Equipment
Inspections throughout North America
203-628-4325 info@cvigna.com

Make:	Bobcat	Type:	TRACTOR	Inspector:	AM
Model:	CT2025H	Hours:	72	Inspection Date:	12/13/2024
SN:	B4VH17854	Year:	2023		

SPECIFICATIONS

ROPS:	No	Hours:	72			
Enclosed Cab:	No	Cab Heat:	No	Cab A/C:	No	Controls: Standard
Attachment on Machine:	BOBCAT CTLOADER FL7 B4V207560					
Additional Attachments:	BOBCAT BACKHOE B4V302642					
2-Speed:	Yes	Engine MFR:	DAEDONG	Tires		
High Flow Hydraulics - Sticker:	No	Power Bob-Tach:	No	Keyless Start:	No	
Backup Camera:	No	Ride Control:	No	Deluxe Instrumentation:	No	
Hydraulic X-Change:	No					
Comments and Defects:	ALMOST NEW,					

BOBCAT EQUIPMENT CONDITION REPORT

For more information, visit:
wellsfargo.com/equipseller



Commerical Vehicle Inspection Group
Truck, Tractor, Trailer, and Equipment
Inspections throughout North America
203-628-4325 info@cvigna.com

Tire Fault Legend			
C - Cut	D - Dry	F - Flat	M - Mismatched Tread / Casings
WD - Wheel Damage			

FRONT AXLE		
Make: GALAXY Part #: Measure: 15 / 32 Condition: GOOD Tread Remaining: Over 50% Fault:		Make: GALAXY Part #: Measure: 15 / 32 Condition: GOOD Tread Remaining: Over 50% Fault:

REAR AXLE		
Make: GALAXY Part #: Measure: 24 / 32 Condition: GOOD Tread Remaining: Over 50% Fault:		Make: GALAXY Part #: Measure: 24 / 32 Condition: GOOD Tread Remaining: Over 50% Fault:

BOBCAT EQUIPMENT CONDITION REPORT

For more information, visit:
wellsfargo.com/equipmentseller



Commerical Vehicle Inspection Group
Truck, Tractor, Trailer, and Equipment
Inspections throughout North America
203-628-4325 info@cvigna.com

CONDITION REPORT

Check	Comments / Deficiencies
✓ Visual Inspection	CLEAN
✓ Operational Test	PASSED - MOVED FORWARD/BACK WARD - LIFTED UP AND DOWN
✓ Lift Cylinders	NO LEAKS
✓ Tilt Cylinders	NO LEAKS
✓ Boom Arms Operations	WORKING
✓ Seat	GOOD CONDITION
✓ Tailgate Lights	GOOD CONDITION
✓ Working Lights	GOOD CONDITION
✓ Front Door	NO DAMAGES
N/A Rear and Top Window	
N/A Side Glass Complete	
✓ Boom Arms Damages	NO DAMAGES
N/A Rear Door	
✓ Mufflers	GOOD CONDITION
N/A ROPS Condition	
N/A Power Bob-Tach Condition	
N/A Cab A-C Condition	
N/A Cab Heat Condition	
✓ Intake Screen	GOOD CONDITION
✓ Eng. Compartment	
✓ Hydraulic X-Change Condition	OPERATIONAL
✓ Customer Decals Visible on Unit	NO
✓ Error Codes	
X Condition Report	HAS A FEW SMALL DENTS ON HOOD

PHOTOS



Front Left



Front Right



PHOTOS



Rear



PHOTOS



Seating / Interior

PHOTOS



Seating / Interior

PHOTOS



PHOTOS



PHOTOS



PHOTOS



PHOTOS



PHOTOS



PHOTOS



PHOTOS

