

INSPECTION SUMMARY**2017 Agco/Challenger Rogator 1300B Fertilizer Spreader**

Sikeston, Missouri
SN AGCA1300CHNS31112

July 31, 2020

Equipment Inspection Location: 2907 State Highway 62, Sikeston, Missouri**Inspection Date:** July 30, 2020**Description:** 2017 Agco/Challenger Rogator 1300B Fertilizer Spreader**Serial Number:** AGCA1300CHNS31112**Hours:** 1759 Metered Hours**General Description:** Cab, 253-HP Diesel Engine, Hydrostatic Transmission, Valmar Airmax AM180 Row Crop Dry Fertilizer Spreader (SN 18017013), Steel Fertilizer Box with Stainless Steel Insert, Agri-Cover SRT-2 Spool Roll Tarp, Dual 14" Steel Mesh Conveyors, 60' Air Boom, Hydraulic Fold, Raven Monitor, Rear Camera, Ballast Package, Front and Rear Fenders, 380/90R46 Tires (Fair)**Cab:** Good condition. The interior of the cab is in overall good condition. No apparent odor and not excessively dirty.**Cab Glass:** Good condition. No chips, cracks or window fogging.**Cab Systems:** Good condition. No dash warning lights displayed. All lights, backup camera, heat and A/C functioning and maintained.**Cab Components:** Raven GPS System and monitor. Good condition. Appear to be functioning and maintained.**Engine:** 253-HP Diesel Engine. Good condition. Readily starts and shuts down crisply.**Transmission:** Hydrostatic Transmission. Good condition. Seemed to shift properly.**Tires:** 380/90R46 Tires. Fair condition. No side wall damage or weather cracking. (1) Tire approx. 60% tread life remaining, (2) tires approx. 40% tread life remaining and (1) tire approx. 0% tread life remaining.**Mechanical Condition:** Good condition. This unit runs, drives and operates as it was manufactured to do. The conveyors are in working order. The air booms are straight and in working order.**Applicator Components:** Good to average condition. The steel portion of the fertilizer box is showing some rust, the stainless steel insert is in average condition. The conveyors, air booms and the tarp are in good condition and functioning.**Exterior Condition:** Average condition. There are no scratches or peeling paint on the cab and engine cover, but there is some sun fading. The air booms are straight and functioning. There is some scattered rust on the frame, stairs and fertilizer box which is average for the age and use of this unit.**Overall Condition:** Good to average condition. This unit runs, drives and operates as it was manufactured to do.**Maintenance:** No maintenance records were provided as the contact was not the end user of the equipment.**Estimate of Repairs:** N/A**Inspector Notes:** This unit runs, drives and operates as it was manufactured to do. The tires should be replaced.

EQUIPMENT INSPECTION

2017 Agco/Challenger Rogator 1300B Fertilizer Spreader
SN AGCA1300CHNS31112
Sikeston, Missouri

July 31, 2020

Representative Pictures



EQUIPMENT INSPECTION

2017 Agco/Challenger Rogator 1300B Fertilizer Spreader
SN AGCA1300CHNS31112
Sikeston, Missouri

July 31, 2020

Representative Pictures



EQUIPMENT INSPECTION

2017 Agco/Challenger Rogator 1300B Fertilizer Spreader
SN AGCA1300CHNS31112
Sikeston, Missouri

July 31, 2020

Representative Pictures



EQUIPMENT INSPECTION

2017 Agco/Challenger Rogator 1300B Fertilizer Spreader
SN AGCA1300CHNS31112
Sikeston, Missouri

July 31, 2020

Representative Pictures



EQUIPMENT INSPECTION

2017 Agco/Challenger Rogator 1300B Fertilizer Spreader
SN AGCA1300CHNS31112
Sikeston, Missouri

July 31, 2020

Representative Pictures



EQUIPMENT INSPECTION

2017 Agco/Challenger Rogator 1300B Fertilizer Spreader
SN AGCA1300CHNS31112
Sikeston, Missouri

July 31, 2020

Representative Pictures



EQUIPMENT INSPECTION

2017 Agco/Challenger Rogator 1300B Fertilizer Spreader
SN AGCA1300CHNS31112
Sikeston, Missouri

July 31, 2020

Representative Pictures



EQUIPMENT INSPECTION

2017 Agco/Challenger Rogator 1300B Fertilizer Spreader
SN AGCA1300CHNS31112
Sikeston, Missouri

July 31, 2020

Representative Pictures



EQUIPMENT INSPECTION

2017 Agco/Challenger Rogator 1300B Fertilizer Spreader
SN AGCA1300CHNS31112
Sikeston, Missouri

July 31, 2020

Representative Pictures



EQUIPMENT INSPECTION

2017 Agco/Challenger Rogator 1300B Fertilizer Spreader
SN AGCA1300CHNS31112
Sikeston, Missouri

July 31, 2020

Representative Pictures




EQUIPMENT INSPECTION

2017 Agco/Challenger Rogator 1300B Fertilizer Spreader
SN AGCA1300CHNS31112
Sikeston, Missouri

July 31, 2020

Representative Pictures



EQUIPMENT INSPECTION

2017 Agco/Challenger Rogator 1300B Fertilizer Spreader
SN AGCA1300CHNS31112
Sikeston, Missouri

July 31, 2020

Representative Pictures



EQUIPMENT INSPECTION

2017 Agco/Challenger Rogator 1300B Fertilizer Spreader
SN AGCA1300CHNS31112
Sikeston, Missouri

July 31, 2020

Representative Pictures



EQUIPMENT INSPECTION

2017 Agco/Challenger Rogator 1300B Fertilizer Spreader
SN AGCA1300CHNS31112
Sikeston, Missouri

July 31, 2020

Representative Pictures



EQUIPMENT INSPECTION

2017 Agco/Challenger Rogator 1300B Fertilizer Spreader
SN AGCA1300CHNS31112
Sikeston, Missouri

July 31, 2020

Representative Pictures



EQUIPMENT INSPECTION

2017 Agco/Challenger Rogator 1300B Fertilizer Spreader
SN AGCA1300CHNS31112
Sikeston, Missouri

July 31, 2020

Representative Pictures

