

### **Aspen Field Services**

Job #: 25626 / Serial #: H2070287

# For more information, visit: wellsfargo.com/equipmentseller









#### Video:



PHOTOS: Click the link below to view all high resolution images

https://app.staging.aspenfieldservices.com/api/attachments/get/
dj2kfMJxBS4zonySX/full\_report\_0025626\_dj2kfMJxBS4zonySX.pdf?view

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	2016
Make	Hamm
Model	HD120IVO
Serial Number	H2070287
Туре	Roller
Inspection Date	11/10/2020
Location of Business	JJ Kane Auctioneers - 14354 Dearborn Ave , South Beloit, IL 61080
Attachment(s)/ Accessory(s)	None
Enclosed Cab	No
Engine MFR	Hamm
Controls	Standard
Hours	965
Cab A-C	No
Cab Heat	No
Deluxe Instrumentation	No





## Aspen Field Services

Job #: 25626 / Serial #: H2070287

# For more information, visit: wellsfargo.com/equipmentseller

Inspection Details Cont'd		
Keyless Start	No	
Visual Inspection	Clean	
Operations Test	Operational	
Front Roller Condition	Good Condition	
Front Roller Thickness	3/4"	
Front Roller Width	78"	
Front Roller Depth Percentage	Above 50%	
Rear Roller Condition	Good Condition	
Rear Roller Thickness	1"	
Rear Roller Width	78"	
Rear Roller Depth Percentage	Above 50%	
Seat	Good Condition	
Tailgate Lights	Good Condition	
Working Lights	Good Condition	
ROPS Condition	Good Condition	
Engine Door	Opens and Closes	
Intake Screen	Good Condition	
Articulation Cylinder	Good Condition	
Interior Condition	Good	
Engine Compartment	Dirty	
Customer Decals Visible on Unit	Yes	
Comments		

### Inspection Details Cont'd