



Video:



PHOTOS: Click the link below to view all high resolution images

https://app.aspenfieldservices.com/api/attachments/get/_jKbcpoTj9FhNpjpJX/full_report_0026173_jKbcpoTj9FhNpjpJX.pdf?view

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	2014
Model	Hercules
Serial Number	LGN-995971114
Type	Railcar Mover
Inspection Date	12/23/2020
Location of Business	JJ Kane Auctioneers - 999 Solon Rd , Waxahachie, TX 75165
Enclosed Cab	Yes
Controls	Standard
Hours	Not Available
Cab A-C	Yes
Cab Heat	Yes
Cab A-C Condition	NA
Cab Heat Condition	NA
Backup Camera	Yes
Keyless Start	No



Aspen Field Services

Job #: 26173 /

Serial #: LGN-995971114

For more information, visit:

wellsfargo.com/equipmentseller

2014 HERCULES TRACKMOBILE RAILCAR
MOVER

Inspection Details Cont'd	
Visual Inspection	Clean
Operational Test	Does Not Start
Front Right Tire Part Number	Trackmobile: 1080893
Front Right Tire Condition	Flat
Front Right Tire Depth Measurement	15/32"
Front Right Tire Size	9.00-20
Front Left Tire Part Number	Trackmobile: 1080893
Front Left Tire Condition	Good Condition
Front Left Tire Depth Measurement	23/32"
Front Left Tire Size	9.00-20
Back Right Tire Part Number	Ameri-Steel: Not Available
Back Right Tire Condition	Good Condition
Back Right Tire Depth Measurement	15/32"
Back Right Tire Size	11R22.5
Back Left Tire Part Number	Trackmobile: 1080893
Back Left Tire Condition	Good Condition
Back Left Tire Depth Measurement	18/32"
Back Left Tire Size	9.00-20
Back Left Drive Hub	Good Condition
Back Right Drive Hub	Good Condition
Front Left Drive Hub	Good Condition
Front Right Drive Hub	Good Condition
Front Coupler Lift Cylinder	Good Condition
Rear Coupler Lift Cylinder	Good Condition
Left Wheel Cylinder	Good Condition
Right Wheel Cylinder	Good Condition
Tailgate Lights	NA
Working Lights	NA
Cab Door	Good Condition
Passenger Door	Good Condition
Side Glass Complete	Yes
Seat	Good Condition
Muffler	Good Condition
Intake Screen	Good Condition
Engine Compartment	Dirty
Customer Decals Visible on Unit	No
Backup Camera	Yes
Engine Door	Good Condition
Attachment(s)	None
Mismatched Tires	Yes

Inspection Details Cont'd	
Make	Trackmobile
Engine MFR	Trackmobile
Engine Serial Number	73741854
Comments	The back right tire is low on air.