

Aspen Field Services

Job #: 24405 / Serial #: H2430055

For more information, visit: wellsfargo.com/equipmentseller









Video:




PHOTOS: Click the link below to view all high resolution images

 $\frac{https://app.staging.aspenfieldservices.com/api/attachments/get/S3HS2zhrFmsDQrwsG/report_0024405_S3HS2zhrFmsDQrwsG.pdf}{}$

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details		
Master Lease Number	001-0436024-107	
Year	2017	
Make	Hamm	
Model	HD120i VV HF	
Serial Number	H2430055	
Туре	Roller	
Inspection Date	9/16/2020	
Location of Business	JJ Kane Auctioneers - 95 3rd St N , Graysville, AL 35073, USA	
Attachment(s)	None	
Enclosed Cab	No	
Engine MFR	Deutz	
Controls	Standard	
Cab A-C	None	
Cab Heat	None	
Deluxe Instrumentation	None	





Aspen Field Services Job #: 24405 /

Serial #: H2430055

For more information, visit: wellsfargo.com/equipmentseller

Inspection Details Cont'd		
Keyless Start	No	
Visual Inspection	Clean	
Operations Test	Pass	
Front Roller Condition	Good Condition	
Front Roller Thickness	3/4"	
Front Roller Diameter	54"	
Front Roller Width	78"	
Rear Roller Condition	Good Condition	
Rear Roller Thickness	3/4"	
Rear Roller Diameter	53"	
Rear Roller Width	78"	
Front and Rear Depth Percentage	Above 50%	
Seat	Good Condition	
Tailgate Lights	Non Operational	
Working Lights	Good Condition	
ROPS Condition	Good	
Engine Door	Good Condition	
Intake Screen	Good Condition	
Articulating Cylinder	Good Condition	
Interior Condition	Good	
Engine Compartment	Clean	
Customer Decals Visible on Unit	None	
Hours	2574	
Comments	The working lights and tailgate lights are non operational.	

Inspection Details Cont'd