

CONSTRUCTION EQUIPMENT CONDITION REPORT

For more information, visit:
wellsfargo.com/equipmentseller



Commerical Vehicle Inspection Group
Truck, Tractor, Trailer, and Equipment
Inspections throughout North America
203-628-4325 info@cvigna.com

Make: Komatsu	Type: DOZER	Inspector: GP
Model: D61PXi24	Hours: 7380	
SN: KMT0D129AKBB61145	Year: 2019	Inspection Date: 8/30/2024

SPECIFICATIONS

Tracks	Tracks Model: SINGLE GROUSER	Cut: No	Controls: FWD - REV - LEFT - RIGHT - RAISE / LOWER CUTTER
	Tread Depth: 55/32	Tread %: Over 50%	
Enclosed Cab: Yes	Heat: Yes	A/C: Yes	
Bucket Width: 151	Teeth: Without	Damaged: Yes	
Other Options:	12'5" BLADE - TILTS AND SWINGS SIDE TO SIDE REAR CAMERA		

CONDITION REPORT

Check	Comments / Deficiencies
✓ Frame	
X Boom & Uprights	WORN PINS / BUSHINGS AT BLADE FRAME LIFT ARMS WHEN TILTING BLADE
✓ Lift Cylinders	
✓ Tilt Cylinders	
✓ R H Drive	
✓ L H Drive	
✓ Variable Speed	
✓ Engine	QUIET
✓ Appearance	AVERAGE
N/A Describe Missing Parts	
X Attachment Inspection	TOP EDGE OF PUSH BLADE TORN
X Condition Report	LEFT / RIGHT SIDES CARRIER ROLLERS WORN

PHOTOS



Seating / Interior



Rear



Front Right



Front Left

PHOTOS



PHOTOS



PHOTOS



PHOTOS



PHOTOS



PHOTOS



PHOTOS



PHOTOS

