



# Aspen Field Services

Job #: 33826 /

Serial #: NDC10002

For more information, visit:

[wellsfargo.com/equipseller](https://wellsfargo.com/equipseller)

## CAT 352F EXCAVATOR



Video:



**PHOTOS:** Click the link below to view all high resolution images

[https://app.aspenfieldservices.com/api/attachments/get/tLWt3Yxj2sM9Ni6sD/full\\_report\\_0033826\\_tLWt3Yxj2sM9Ni6sD.pdf?view](https://app.aspenfieldservices.com/api/attachments/get/tLWt3Yxj2sM9Ni6sD/full_report_0033826_tLWt3Yxj2sM9Ni6sD.pdf?view)

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	Not Available
Make	CAT
Model	352F
VIN	CAT0352FLNDC10002
Type	Excavator
Inspection Date	09/16/2021
Location of Business	JJ Kane Auctioneers 95 3rd St NE, Graysville, AL, 35073, USA
Hours	7040
Operational Test	Passed - Operational
Attachment	None
Enclosed Cab	Yes
Controls	Standard
Cab A/C	Yes
Cab A/C Condition	Good Condition
Cab Heat	Yes



# Aspen Field Services

Job #: 33826 /

Serial #: NDC10002

CAT 352F EXCAVATOR

For more information, visit:

[wellsfargo.com/equipmentseller](https://wellsfargo.com/equipmentseller)

Inspection Details Cont'd	
Cab Heat Condition	Good Condition
Backup Camera	Yes
Backup Camera Condition	Good Condition
Keyless Start	No
Visual Inspection	Fair
Bucket Cylinder	Missing
Boom Arm	Good Condition
Boom Arm Cylinder	Good Condition
ROPS Condition	Fair - See Notes
Cab Glass Condition	Good Condition
Front Door	Good Condition
Seat Condition	Good Condition
Muffler	Not Available
Intake Screen	Good Condition
Interior	Good Condition
Headlights	None
Working Lights	Not Operational
Engine Compartment	Damaged
Engine Manufacturer	Not Available
Active Warnings	Not Available - See Notes
Left Track Condition	Good Condition
Left Track Tread Depth Percentage	NA - Metal Tracks
Left Track Brand	Not Available
Left Track Sprocket	Good Condition
Left Track Idler	Good Condition
Left Track Rollers	Good Condition
Right Track Condition	Good Condition
Right Track Tread Depth Percentage	NA - Metals Tracks
Right Track Brand	Good Condition
Right Track Sprocket	Good Condition
Right Track Idler	Good Condition
Right Track Rollers	Good Condition
Mismatched Tracks	No

Inspection Details Cont'd
---------------------------



## Aspen Field Services

Job #: 33826 /

Serial #: NDC10002

For more information, visit:

[wellsfargo.com/equipmentseller](https://wellsfargo.com/equipmentseller)

CAT 352F EXCAVATOR

Stick Attachment	Missing
Comments	The ROPS front cab protection is damaged. Engine door is damaged. There is a warning light on, could not be identified - "engine fault, check engine". The stick or dipper has been removed and is missing from boom. The bucket cylinder is missing. No attachments with unit. There is damage to the steps and the grab irons.