



Aspen Field Services

Job #: 24408 /

Serial #: H2430056

For more information, visit:

wellsfargo.com/equipseller

2017 HAMM HD120I VV HF



Video:



PHOTOS: Click the link below to view all high resolution images

https://app.staging.aspenfieldservices.com/api/attachments/get/RyPhj5R6gj3hKiL7W/report_0024408_RyPhj5R6gj3hKiL7W.pdf

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

| Inspection Details | |
|----------------------|--|
| Master Lease Number | 001-0436024-104 |
| Year | 2017 |
| Make | Hamm |
| Model | HD120i VV HF |
| Serial Number | H2430056 |
| Type | Roller |
| Inspection Date | 9/16/2020 |
| Location of Business | JJ Kane Auctioneers - 95 3rd St NE , Graysville, AL, 35073 |
| Attachment(s) | None |
| Enclosed Cab | No |
| Engine MFR | Deutz |
| Controls | Standard |
| Hours | 2451 |
| Cab A-C | No |
| Cab Heat | No |



Aspen Field Services

Job #: 24408 /

Serial #: H2430056

2017 HAMM HD120I VV HF

For more information, visit:

wellsfargo.com/equipmentseller

| Inspection Details Cont'd | |
|--|--|
| Deluxe Instrumentation | None |
| Keyless Start | No |
| Visual Inspection | Clean |
| Operations Test | Passed |
| Front Roller Condition | Good Condition |
| Front Roller Thickness | 3/4" |
| Front Roller Diameter | 55" |
| Front Roller Width | 78" |
| Rear Roller Condition | Good Condition |
| Rear Roller Thickness | 3/4" |
| Rear Roller Diameter | 55" |
| Rear Roller Width | 78" |
| Front and Rear Roller Depth Percentage | Above 50% |
| Seat | Good Condition |
| Tailgate Lights | Good Condition |
| Working Lights | Non Operational |
| ROPS Condition | Good Condition |
| Engine Door | Good Condition |
| Intake Screen | Good Condition |
| Articulation Cylinder | Good Condition |
| Interior Condition | Good Condition |
| Engine Compartment | Clean |
| Customer Decals Visible on Unit | No |
| Comments | Both working lights are non operational. |

Inspection Details Cont'd