



DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR QUICK CHECK INSPECTION

INSPECTOR: 5750
INSPECTION ID
117883

CLIENT
 504 - Wells Fargo MSG
INSP DATE | **FLEET NAME** | **VIN (LAST 8)** | **PO NUMBER**
 05/19/2020 | | FT080182 |

Year, Make:	2015, JOHN DEERE	Full VIN:	1TC200GXVFT080182
Model:	HD200	Engine Make:	JOHN DEERE
Engine Model:		Clean air idle:	
Classification:	Utility vehicle		

Note and photograph any body damage including scrapes, dents and glass:
 GOOD

Note and photograph any major oil or fluid leaks:
 GOOD

Note and photograph any damage including abnormal wear, holes, tears and waffling in trailer walls.
 GOOD

Note any unusual engine noises or knocks:
 GOOD

List and photograph any tires with uneven wear:
 ALL WORN UNDER 50%

Additional Comments:

Additional Services	Requested	Status	Comments
---------------------	-----------	--------	----------

ITEMS	COMMENTS
ALL TIRES WORN	UNDER 50%
HOURS 3205	



DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR QUICK CHECK INSPECTION

CLIENT
 504 - Wells Fargo MSG
 INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER
 05/19/2020 | | FT080182 |

INSPECTOR: 5750
 INSPECTION ID
 117883



LEFT REAR



VIN



RIGHT FRONT



RIGHT REAR



REAR



HOUR METER



CONTROLS



SEATS



ENGINE TAG



ENGINE



TIRES



ADDITIONAL 4



ADDITIONAL 6



ADDITIONAL 16



ADDITIONAL 7



ADDITIONAL 8



DEKRA Services Inc.
Customer Service 770-257-0107

TRACTOR QUICK CHECK INSPECTION

CLIENT
504 - Wells Fargo MSG
INSP DATE | FLEET NAME | VIN (LAST 8) | PO NUMBER
05/19/2020 | | FT080182 |

INSPECTOR: 5750
INSPECTION ID
117883



ADDITIONAL 10



ADDITIONAL 11



ADDITIONAL 14



ADDITIONAL 15