



Video:



**PHOTOS:** Click the link below to view all high resolution images

[https://app.aspenfieldservices.com/api/attachments/get/RcME9ehvDZNutJ9J/full\\_report\\_0026176\\_RcME9ehvDZNutJ9J.pdf?view](https://app.aspenfieldservices.com/api/attachments/get/RcME9ehvDZNutJ9J/full_report_0026176_RcME9ehvDZNutJ9J.pdf?view)

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	2018
Make	Volvo
Model	EC750EL
PIN	VCEC750EL00310160
Type	Excavator
Inspection Date	12/23/2020
Location of Inspection	JJ Kane Auctioneers - 999 Solon Rd, Waxahachie, TX 75165
Hours	3810
Attachment	Bucket Serial Plate Not Visible
Enclosed Cab	Yes
Controls	Standard
Cab A/C	Yes
Cab A/C Condition	Good Condition
Cab Heat	Yes
Cab Heat Condition	Good Condition



# Aspen Field Services

Job #: 26176 /

Serial #: 310160

For more information, visit:

[wellsfargo.com/equipmentseller](http://wellsfargo.com/equipmentseller)

2018 VOLVO EC750E EXCAVATOR

Inspection Details Cont'd	
Backup Camera	Yes
Keyless Start	No
Visual Inspection	Clean
Operations Test	Operational
Left Track Condition	Good Condition
Left Track Tread Depth Measurement	2 1/4"
Left Track Tread Depth Percentage	NA Metal Tracks
Left Track Brand	Not Available
Left Track Sprocket	Good Condition
Left Track Idler	Good Condition
Left Track Rollers	Good Condition
Right Track Condition	Good Condition
Right Track Tread Depth Measurement	2 1/4"
Right Track Tread Depth Percentage	NA Metal Tracks
Right Track Brand	Not Available
Right Track Rollers	Good Condition
Right Track Sprockets	Good Condition
Right Track Idler	Good Condition
Mismatched Tracks	No
Bucket Cylinder	Good Condition
Stick Cylinder	Good Condition
Boom Cylinders	Good Condition
Boom Arm	Operational
Boom Arm Condition	Good Condition
ROPS Condition	Good Condition
Glass Condition	Good Condition
Front Door	Good Condition
Seat Condition	Good Condition
Muffler	Good Condition
Intake Screen	Good Condition
Interior	Good Condition
Headlights	Non Operational
Working Lights	Non Operational
Engine Compartment	Dirty
Engine Manufacturer	Volvo
Active Warnings	None
Comments	The left cab head light is non operational. A working light on the boom arm's left side is non operational.

## Inspection Details Cont'd