

ITEM DETAILS - 2023 Tigercat

Thursday, March 05, 2026

DETAILED EQUIPMENT INFORMATION

A qualified Ritchie Bros. employee collected detailed equipment information and performed functional tests on the key components of this asset.

General Appearance

Serial Number / VIN: 6023037

Serial Number Location: Rear Frame Passenger Side

CE Mark: No CE mark found


Seller Reference Number: Seller Reference or Fleet Number:, 602

Tires/ Undercarriage: Percentage Rating:, 30

Hour Meter / Odometer: 744 hrs

Condition: Overall Condition for Age:, Fair

Features: Air Conditioner, Joystick Steering, Blade, Tigercat Grapple, Double Arch, Paccar Single Drum Winch, 28L26 Tires



Model Description

Model Description: 4x4

Control Station

Control Station: Air Conditioner, Joystick Steering



Engine

Engine: No US EPA Label Present

Limited Function Check: The engine started and ran.




Drivetrain

Limited Function Check: The drivetrain was operational.




Hydraulics

Limited Function Check: The hydraulic system was operational.



Chassis

Front Attachment: Blade
Rear Attachment: Grapple Skidder: Tigercat Grapple, Arch/Boom Type:
Double Arch, Paccar Single Drum Winch



Undercarriage

Undercarriage: 28L26 Tires



DISCLAIMER

General

The Detailed Equipment Information is limited in scope, and Ritchie Bros. Auctioneers has not inspected any aspects or components of the equipment other than those expressly set forth herein. Unless expressly stated, we make no representations or warranties, express or implied, concerning the equipment or its components, including without limitation any representations or warranties concerning functionality, conformity or compliance with any safety standard or requirement of any applicable authority or regulatory body, fitness for any particular purpose, or merchantability. You are strongly advised to perform your own detailed inspection of the equipment prior to bidding.

Functions

Equipment is not tested under load. We make no representation or warranty that equipment is operating in accordance with manufacturers' specifications. No inspection has been performed with respect to any functionality aspect other than those expressly included herein. Only select photos have been provided for individual undercarriage components, and may not be indicative of the condition of the entire undercarriage as a whole.

Dimensions

Measurements are given as an estimate only. Actual loaded dimensions may vary based on truck/trailer height and the loaded machine configuration/position. It is the buyer's responsibility to measure all loads before leaving our auction site to ensure the load is safe for transport. All measurements should be verified by the buyer. DO NOT rely on these measurements for transportation purposes