

# 2024 VERMEER SC382

UNIT: 1VRU112BLR1001924

[Download Reconditioning Printout](#)



## UNIT SPECS

Customer Wells Fargo (IMS)

## LOCATION

Wells Fargo (IMS)   
Please call Pickup Support for location information  
Davenport, FL 33897

## CHASSIS

Holders And Cutting Bits  
Rating:  
Good

Limited Function Check (Chassis)

The main chassis components were operational in a limited check.

Features

20 in Grinding Wheel

## CONTROL STATION

Gauges

Operational

Warning Lights

Operational

Limited Function Check (Control Station)

The main components are in place and operational as noted.



Drivetrain

Hydrostatic Drive

## DRIVETRAIN

Transmission Type

Hydrostatic

Drive Motors

Rating:

Good

Limited Function Check (Drivetrain)

The drivetrain was operational.

## ENGINE

Blow-by (Subjective Visual Observation)

Recirculating system

Starter

Operational

Fuel System

Operational

Limited Function Check (Engine)

The engine started and ran.



Emissions Status #2

US EPA Label

Engine

Briggs & Stratton Vanguard 2 Cylinder Gasoline Engine

## GENERAL APPEARANCE

Year

2024

Make  
Vermeer

Model  
SC382

Serial Number / VIN  
1VRU112BLR1001924

Seller Reference Number  
Seller Reference or Fleet Number:, B75/69

Hour Meter /Odometer Usage Reading (Start)  
48 hrs

Hour Meter / Odometer  
49 hrs

Condition  
Fair

## HYDRAULICS

Pumps (Hydraulics)  
Rating:  
Good

Valves  
Rating:  
Good

Hydraulic Tank  
Rating:  
Good

Bar Lift Cylinders  
Rating:  
Good

Blade Cylinders  
Rating:  
Good

Limited Function Check (Hydraulics)  
The hydraulic system was operational.

## LOGISTICS INFORMATION

General Shipping Information  
Yes: Does this Unit Run? Yes: If self propelled, does the unit travel? Yes: Inflated Tires - item can roll? No: Is the unit taller than 12'? No: Is the unit wider than 8'6"? No: Noticeable fluid leaks?

## TRAILER

Features  
20 in Grinding Wheel

## **MODEL DESCRIPTION**

Model Description  
4x4

## **RECONDITIONING**