




Video:



PHOTOS: Click the link below to view all high resolution images

https://app.aspenfieldservices.com/api/attachments/get/bthhcHrCrkTK5JzWi/report_0024727_bthhcHrCrkTK5JzWi.pdf

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	2015
Make	JCB
Model	3CX-14L4CA
PIN	JCB3CXAPP02268516
Type	Backhoe Loader
Inspection Date	9/29/2020
Location of Business	JJ Kane Auctioneers - Waxahachie; 999 Solon Rd , Waxahachie, TX 75165
Enclosed Cab	No
Attachment(s)/ Accessory(s)	333/E0505 Bucket SN Not Available Bucket SN Not Available
Engine MFR	Not Visible
Engine Compartment	Dirty
Controls	Standard
Hours	472
Cab A/C	No
Cab A/C Condition	NA



Aspen Field Services

Job #: 24727 /

Serial #: 2268516

For more information, visit:

wellsfargo.com/equipmentseller

2015 JCB 3CX-14 BACKHOE LOADER

Inspection Details Cont'd	
Cab Heat	No
Cab Heat Condition	NA
Backup Camera	No
Advanced Instrumentation	No
Keyless Start	No
Visual Inspection	Clean
Operational Test	Passed
Front Right Tire Condition	Flat
Front Right Tire Part Number	Galaxy
Front Right Tire Depth Percentage	32%
Front Right Tire Depth Measurement	9/32"
Front Right Tire Size	14 x 17.5
Front Left Tire Condition	Cut
Front Left Tire Part Number	Galaxy
Front Left Tire Depth Percentage	32%
Front Left Tire Depth Measurement	9/32"
Front Left Tire Size	14 x 17.5
Back Right Tire Condition	Good Condition
Back Right Tire Part Number	Galaxy
Back Right Tire Depth Percentage	76%
Back Right Tire Depth Measurement	22/32"
Back Right Tire Size	19.5L x 24
Back Left Tire Condition	Good Condition
Back Left Tire Part Number	Galaxy
Back Left Tire Depth Percentage	66%
Back Left Tire Depth Measurement	19/32"
Back Left Tire Size	19.5L x 24
Mismatched Tires	No
Lift Cylinders	No Leaks
Tilt Cylinders	No Leaks
Swing Cylinders	No Leaks
Boom Cylinders	No Leaks
Bucket Cylinders	No Leaks
Stabilizer Cylinders	No Leaks
Boom Arm Operations	Operational
Seat	Tear
Tailgate Lights	Good Condition
Working Lights	Good Condition
Side Door	NA

Inspection Details Cont'd	
Glass Complete	NA
Boom Arm Damages	None
Engine Hood	Opens and Stays Closed
Intake Screen	Good Condition
Muffler	Good Condition
Interior	Fair
Customer Decals Visible on Unit	Yes
Stabilizing Arms	Good Condition
Comments	The front right tire is flat. The cushion on the arm rest is missing. The PIN was listed on the plate, but the serial number does match the last few digits.