



Buy this item and view more at www.ironplanet.com or call 800-211-3983

Item #9831962 - Kuhn VXL 1180 x 0 ft Feed Mixer



Item Details:

- Features: 1000 PTO
- Meter Reading: Not Available
- Serial # : B0051
- Inspection Completed: 5/1/23

Shipping Details:

- Location Utah (Juab County)
- Loading Dock Available: No

Inspection Report

Note: This condition inspection report is the result of an impartial, systematic, documented process focused on the establishment of the general, overall mechanical condition of a piece of equipment, or of a vehicle, at a specific time. The purpose of the inspection is to establish the "as is" operational capability of the machine. It is not a performance or load test on the item.

Inspection Ratings Key


★★★★	Limited use or recently replaced. Free of visible wear or defects.
★★★☆☆	Performs within the tolerances expected for age and type of item
★★☆☆☆	Although performing, shows indication of needing repair or replacement
★☆☆☆☆	Needs immediate repair/replacement. Requires work if it is to perform as expected

General Appearance

Item	Assessment	Photo
Picture, Left Front Corner		
Picture, Left Rear Corner		
Picture, Right Rear Corner		
Picture, Right Front Corner		

Serial Number / VIN	B0051	
Paint		
Sheet Metal (fiberglass) Condition		
Steps/Ladders		
Hand Rails		
General Appearance #1		
General Appearance #2		

General Appearance #3		
General Appearance #4		
General Appearance #5		
General Appearance #6		
General Appearance #7		
General Appearance #8		
General Appearance #9		

General Appearance #10		
General Appearance #11		
General Appearance #12		
General Appearance #13		
General Appearance #14		
General Appearance #15		
General Appearance #16		

General Appearance #17		
General Appearance #18		
General Appearance #19		
General Appearance #20		
General Appearance #21		
General Appearance #22		
General Appearance #23		

General Appearance #24		
General Appearance #25		
General Appearance #26		
General Appearance #27		
General Appearance #28		
General Appearance #29		
General Appearance #30		

Engine		
Item	Assessment	Photo
Hour Meter	0 Not Available	

Hydraulics		
See photos for condition		
Item	Assessment	Photo
Hoses		
Cylinder(s)	☆☆☆☆	
Cylinder Pins and Bushings	☆☆☆☆	
Limited Function Check	The hydraulic system could not be operationally checked.	

Trailer Chassis

IronPlanet pin connection pivot point wear inspections are limited to sound, sight and feel observations. Dial indicator testing is not performed.

Item	Assessment	Photo
Frame Rails/ Main Beams Condition	★★★★☆	
Axle Condition	★★★★☆	
Springs/Hangers Condition	★★★★☆	
Brake Lines/Hoses	★★★★☆	
Limited Function Check - Brakes	The brakes were not operationally checked.	
Tire Condition		
Tires	Left front outer: 21/32", Left front inner: 8/32", Left rear outer: 4/32", Left rear inner: 15/32", Right rear outer: 8/32", Right rear inner: 10/32", Right front outer: 7/32", Right front inner: 7/32"	
Wheel Condition	★★★★☆	
Wheel Studs	★★★★☆	
Tongue/ Hitch Condition	★★★★☆	

Landing Gear / Tongue Jack	★★★★☆	
Power Receptacle Functional	Not operationally checked	
Lights/Wiring Condition	Not operationally checked	
Brake Lights Functional	Not operationally checked	
License Plate Light Functional	No	
Deck/ Floor Condition	★★★★☆	

Buy this item and view more at www.ironplanet.com or call 800-211-3983

IronPlanet, Inc. © 2012 All Rights Reserved