

BOBCAT EQUIPMENT CONDITION REPORT

For more information, visit:
wellsfargo.com/equipseller



Commerical Vehicle Inspection Group
Truck, Tractor, Trailer, and Equipment
Inspections throughout North America
203-628-4325 info@cvig.com

Make:	Bobcat	Type:	Mini Excavator	Inspector:	DB2
Model:	E35i T4	Hours:	1140	Inspection Date:	1/28/2025
SN:	B3Y220752	Year:	2022		

SPECIFICATIONS

ROPS:	Yes	Hours:	1140			
Enclosed Cab:	No	Cab Heat:	No	Cab A/C:	No	Controls: Standard
Attachment on Machine:	N/A					
Additional Attachments:	N/A					
2-Speed:	Yes	Engine MFR:	KUBOTA	Tracks		
High Flow Hydraulics - Sticker:	No	Power Bob-Tach:	No	Keyless Start:	Yes	
Backup Camera:	No	Ride Control:	No	Deluxe Instrumentation:	Yes	
Hydraulic X-Change:	No					
Comments and Defects:	RUNS DRIVES,					

BOBCAT EQUIPMENT CONDITION REPORT

For more information, visit:
wellsfargo.com/equipseller



Commerical Vehicle Inspection Group
Truck, Tractor, Trailer, and Equipment
Inspections throughout North America
203-628-4325 info@cvigna.com

Tire Fault Legend			
C - Cut	D - Dry	F - Flat	M - Mismatched Tread / Casings
WD - Wheel Damage			

TRACKS	
Make: BOBCAT Part #: 7274253 Measure: 32 / 32 Condition: FAIR Tread Remaining: Over 50% Fault: C	Make: BOBCAT Part #: 7274253 Measure: 32 / 32 Condition: FAIR Tread Remaining: Over 50% Fault: C

BOBCAT EQUIPMENT CONDITION REPORT

For more information, visit:
wellsfargo.com/equipmentseller



Commerical Vehicle Inspection Group
Truck, Tractor, Trailer, and Equipment
Inspections throughout North America
203-628-4325 info@cvigna.com

CONDITION REPORT

Check	Comments / Deficiencies
✓ Visual Inspection	CLEAN
✓ Operational Test	PASSED - MOVED FORWARD/BACK WARD - LIFTED UP AND DOWN
✓ Lift Cylinders	NO LEAKS
✓ Tilt Cylinders	NO LEAKS
✓ Boom Arms Operations	WORKING
✓ Seat	GOOD CONDITION
✓ Tailgate Lights	GOOD CONDITION
✓ Working Lights	GOOD CONDITION
N/A Front Door	
N/A Rear and Top Window	
N/A Side Glass Complete	
✓ Boom Arms Damages	NO DAMAGES
✓ Rear Door	OPENS AND CLOSES AND STAYS CLOSED
✓ Mufflers	GOOD CONDITION
X ROPS Condition	ROOF BENT FRONT AND BACK
N/A Power Bob-Tach Condition	
N/A Cab A-C Condition	
N/A Cab Heat Condition	
✓ Intake Screen	GOOD CONDITION
✓ Eng. Compartment	
N/A Hydraulic X-Change Condition	
✓ Customer Decals Visible on Unit	NO
✓ Error Codes	
X Right Track Faults	TRACK IS CUT
X Left Track Faults	TRACK IS CUT
X Condition Report	BLADE DAMAGED/BENT

PHOTOS



Front Left



Front Right



Rear

PHOTOS



Seating / Interior



PHOTOS



PHOTOS



PHOTOS



PHOTOS



PHOTOS

